

WiFi - Bug #655

FD7352S, STA 2.4G

12/09/2024 04:42 PM - EGON

Status:	Closed	Start date:	12/09/2024
Priority:	Urgent	Due date:	
Assignee:	KuangJie	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
OS:		OS:	Ubuntu
CPU:	RK3399	Kernel:	Linux version 5.10.160 (liukuangjie@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #28 SMP Thu Sep 26 15:39:06 CST 2024
Path:	\\192.168.1.250\01-Public\FB101-FD7352S-B\update-sdio.i mg	APP:	
Progress:		Progress:	100%
EMMC:		EMMC:	-

Description

FD7352S, STA 2.4G wifi sh ping

```

-----
Connected to cc:29:bd:0c:0f:61 (on wlan0)
SSID: ceshi
freq: 2462
RX: 0 bytes (0 packets)
TX: 0 bytes (0 packets)
signal: -14 dBm
tx bitrate: 45.0 MBit/s MCS 2 40MHz short GI
-----
Connected to cc:29:bd:0c:0f:61 (on wlan0)
SSID: ceshi
freq: 2462
RX: 0 bytes (0 packets)
TX: 0 bytes (0 packets)
signal: -14 dBm actual rate(Mbps)
tx bitrate: 45.0 MBit/s MCS 2 40MHz short GI
-----

```

Mode	Frequency band	Protocol& bandwidth	UL&DL	actual rate(Mbps)	Target rate (Mbps)
AP	2.4G	n-20	TCP_UL	/	144.4 Mbits/s
			TCP_DL	/	144.4 Mbits/s
			UDP_UL	/	144.4 Mbits/s
			UDP_DL	/	144.4 Mbits/s
		n-40	TCP_UL	/	300 MBit/s
			TCP_DL	/	300 MBit/s
			UDP_UL	/	300 MBit/s
			UDP_TL	/	300 MBit/s
		ax-20	TCP_UL	/	286.6 MBit/s
			TCP_DL	/	286.6 MBit/s
			UDP_UL	/	286.6 MBit/s
			UDP_DL	/	286.6 MBit/s
		ax-40	TCP_UL	/	573.5 MBit/s
			TCP_DL	/	573.5 MBit/s
			UDP_UL	/	573.5 MBit/s
			UDP_DL	/	573.5 MBit/s

History

#1 - 12/16/2024 04:29 PM - EGON

- Priority changed from Normal to Urgent

#2 - 12/23/2024 10:02 AM - EGON

- Status changed from New to Closed

Files

□□□□□_17337334544332.png	19.8 KB	12/09/2024	EGON
□□□□□_173373347340.png	52.4 KB	12/09/2024	EGON