

WIFI - Bug #752

FD7352S-BS AP

12/24/2024 08:28 PM - EGON

Status:	New	Start date:	12/24/2024
Priority:	High	Due date:	
Assignee:	KuangJie	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LZ160	:	Ubuntu
CPU:	RK3588	:	Linux version 5.10.110 (wangxiaocan@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #6 SMP Wed Sep 18 11:27:12 CST 2024
:	LKD3588	APP:	
/:		:	
:	01	:	FD7352S
/:	03	:	
:	\\192.168.1.250\17-OpenImage\near-di- ownload\RK3588\LKD3588\Ubuntu	EMMC:	-

Description

FD7352S AP

Iface: wlan0 (id: 0)
addr: 24:ef:b4:52:5d:e9
mode: AP
cpu_id: -1
max_sta: 31

BSS Info:
SSID: SKW_24G_HT40
BSSID: 24:ef:b4:52:5d:e9
channel: 6
width: 20M

History

- #1 - 12/27/2024 10:25 AM - EGON
- Subject changed from FD7352S AP to FD7352S-BS AP

Files

17350432105300.png	7.92 KB	12/24/2024	EGON
--------------------	---------	------------	------