

WIFI - Bug #753

wifi ping FD7352S-BS

12/24/2024 08:31 PM - EGON

Status:	Closed	Start date:	12/24/2024
Priority:	Urgent	Due date:	
Assignee:	KuangJie	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
OS:	LZ160	OS:	Ubuntu
CPU:	RK3588	OS version:	Linux version 5.10.110 (wangxiaocan@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #6 SMP Wed Sep 18 11:27:12 CST 2024
Model:	LKD3588	APP:	
Model number:		Model:	
Model name:	01	Model:	FD7352S
Model number:	03	Model:	
Model:	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	EMMC:	-

Description

wifi ping FD7352S

SSID:	neardi_5G
协议:	Wi-Fi 4 (802.11n)
安全类型:	WPA2-个人
制造商:	Intel Corporation
描述:	Intel(R) Wi-Fi 6E AX210 160MHz

History

#1 - 12/24/2024 08:31 PM - EGON

- Subject changed from wifi ping FD7352S to wifi ping FD7352S
- Priority changed from Normal to Urgent

#2 - 12/27/2024 10:25 AM - EGON

- Subject changed from wifi ping FD7352S to wifi ping FD7352S-BS

#3 - 12/27/2024 04:44 PM - EGON

Qualcomm FastConnect 6900 Wi-Fi 6E Dual Band Simultaneous (DBS) Wi-Fi Network Adapter
Intel(R) Wi-Fi 6E AX210 160MHz

#4 - 01/08/2025 10:54 AM - KuangJie

bug 764
DRAM IRAM

#5 - 01/08/2025 11:18 AM - EGON

- Status changed from New to Closed

Files

□□□□□_17350434338313.png	10.5 KB	12/24/2024	EGON
--------------------------	---------	------------	------