

WIFI - Bug #760

FD7352S-BS

12/25/2024 06:04 PM - EGON

Status:	New	Start date:	12/25/2024
Priority:	Normal	Due date:	
Assignee:	KuangJie	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LZ160	:	Ubuntu
CPU:	RK3588	:	Linux version 5.10.110 (wangxiaocan@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #6 SMP Wed Sep 18 11:27:12 CST 2024
:	LKD3588	APP:	
/:		:	100%
:	01	:	FD7352S
/:	03	:	
:	\\192.168.1.250\17-OpenImage\neardi-d ownload\RK3588\LKD3588\Ubuntu	EMMC:	-
Description			
FD7352S-BS HP Probook 455 15.6 inch G10 Notebook PC			