


WIFI - Bug #761


FD7352S-BS

12/25/2024 06:07 PM - EGON

Status:	New	Start date:	12/25/2024
Priority:	Normal	Due date:	
Assignee:	KuangJie	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
OS:	LZ160	OS:	Ubuntu
CPU:	RK3588	Kernel:	Linux version 5.10.110 (wangxiaocan@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #6 SMP Wed Sep 18 11:27:12 CST 2024
Model:	LKD3588	APP:	
Board:		Progress:	100%
Port:	01	Device:	
Path:	03	Manufacturer:	
URL:	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	EMMC:	-

Description





History

#1 - 12/25/2024 06:10 PM - EGON

send a file --
Bluetooth Manage send files to devices -- --ok --

#2 - 12/27/2024 10:23 AM - EGON

- Subject changed from to FD7352S-BS

#3 - 12/27/2024 10:28 AM - EGON

changed from \\192.168.1.250\\01-Public\\FB101-FD7352\\FD7352S-B\\update-sdio.img to \\192.168.1.250\\17-OpenImage\\neardi-download\\RK3588\\LKD3588\\Ubuntu

changed from Linux version 5.10.160 (liukuangjie@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #28 SMP Thu Sep 26 15:39:06 CST 2024 to Linux version 5.10.110 (wangxiaocan@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #6 SMP Wed Sep 18 11:27:12 CST 2024

Files

_17351211692556.png	459 KB	12/25/2024	EGON
_17351211923467.png	449 KB	12/25/2024	EGON