

WIFI - Bug #793

FD7352S-BS AP

01/09/2025 01:50 PM - EGON

Status:	New	Start date:	01/09/2025
Priority:	Normal	Due date:	
Assignee:	KuangJie	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
 :	LZ160	 :	
CPU:	RK3588	 :	Linux version 5.10.110 (liukuangjie@ubuntu2204-docker) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #5 SMP Mon Dec 30 14:33:35 CST 2024
 :	LKD3588	APP :	
 / :		 :	<50%
 :	01	 :	FD7352S
 / :	03	 :	
 :	rk3588_debian_wifi_test_7352s_h24.45-B_12_30.img	EMMC :	-
Description			
FD7352S-BS AP			