

KP12C - Bug #808

LP120_4_1080_Ubuntu20.04_v1.0_20250110.img TF

01/15/2025 05:55 PM -

Status:	New	Start date:	01/15/2025
Priority:	High	Due date:	
Assignee:		% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	KP12C	:	Ubuntu
CPU:	RK3568	:	Linux LPA3568 5.10.198 #15 SMP Fri Jan 10 10:58:35 CST 2025 aarch64 aarch64 GNU/Linux
:	"LPA3568M4"	APP:	-
/:	05	:	100%
:	04	:	RTL8852
/:	04	:	YT8521SC
:	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img	EMMC:	-
Description 1SDDiskTool_v1.64TF 2TF 3LZ12000004_DB_T1_V1_230317A.img RK3568			