

LP201 - Bug #811

reboot--SPK pop

01/20/2025 11:06 AM -

Status:	New	Start date:	01/20/2025
Priority:	Normal	Due date:	
Assignee:	shiliang	% Done:	0%
Category:	H.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
OS:	LP201	OS:	Ubuntu
CPU:	RK3576	Kernel:	V6.1.84
GPU:	LPS3576	APP:	-
RAM/Flash:	-	Progress:	100%
Storage:	-	Result:	N/S
RAM/Flash:	01	Serial:	YT8521SC
Image:	ubuntu22.04_lb201_25_01_07.img	EMMC:	-
Description			

History

#1 - 01/22/2025 10:02 AM -

1. pop
POPP
POPP
2. pop pop

#2 - 01/22/2025 10:12 AM -

wrote in [#note-1](#):

1. pop
POPP
POPP
2. pop pop

1 pop pop
2 reboot pop

#3 - 01/22/2025 11:01 AM -

- Category changed from Driver to H.W
- Assignee changed from to shiliang