

LZ201 - Bug #831

pop / reboot

02/13/2025 01:46 PM -

|                 |                                                               |                 |                     |
|-----------------|---------------------------------------------------------------|-----------------|---------------------|
| Status:         | New                                                           | Start date:     | 02/13/2025          |
| Priority:       | Normal                                                        | Due date:       |                     |
| Assignee:       | jing                                                          | % Done:         | 0%                  |
| Category:       | H.W                                                           | Estimated time: | 0.00 hour           |
| Target version: |                                                               | Spent time:     | 0.00 hour           |
| :               | LZ201                                                         | :               | Ubuntu              |
| CPU:            | RK3576                                                        | :               | Linux LB3576 6.1.84 |
| :               | -                                                             | APP:            | -                   |
| /:              | -                                                             | :               | 100%                |
| :               | 01                                                            | :               | FD7352S             |
| /:              | 01                                                            | :               | YT8521SC            |
| :               | \\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23 | EMMC:           | -                   |
| Description     |                                                               |                 |                     |