

LB700 - Bug #873

J2500 gpio101


03/06/2025 02:54 PM -

Status:	Closed	Start date:	03/06/2025
Priority:	Urgent	Due date:	
Assignee:	sun	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LB700	:	Linux Hi3403 4.19.90 #5 SMP Wed Feb 12 14:45:29 CST 2025 aarch64 aarch64 aarch64 GNU/Linux
CPU:	hisi3403	APP:	
:	LBA3403	:	
/:		:	FD7352S
:	01	:	
:	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	EMMC:	-
:	Ubuntu		

Description

echo 101 > /sys/class/gpio/export
echo out > /sys/class/gpio/gpio101/direction
echo 1 > /sys/class/gpio/gpio101/value
echo 0 > /sys/class/gpio/gpio101/value
gpio1010.217Vgpio1.8v3.3v

gpio101



History

#1 - 03/07/2025 03:41 PM -

- Priority changed from High to Urgent

#2 - 03/10/2025 11:55 AM -

- Category changed from H.W to Driver
- Assignee changed from jing to sun

1.8v

#3 - 03/12/2025 10:18 AM - sun

1.
bspmm 0x0102f0160 0x0200
gpio

#4 - 03/14/2025 10:36 AM -

- Status changed from New to Closed

Files

clipboard-202503061453-qb0ii.png	83.3 KB	03/06/2025	
----------------------------------	---------	------------	--