

LC100 - Bug #881

WIFI

03/11/2025 11:17 AM

Status:	Closed	Start date:	03/11/2025
Priority:	Urgent	Due date:	
Assignee:		% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Path:		File:	\\192.168.1.250\01-Public\wilson_test\rk3399\kernel_4_4\ddr4\LZ100X16_00_FT_LB_0508A_ddr4.img
CPU:		OS:	Ubuntu
Kernel:		Kernel version:	Linux bionic 4.4.194 #110 SMP Thu Mar 6 10:24:33 CST 2025 aarch64 aarch64 aarch64 GNU/Linux
RAM:		Flash:	
Flash:	03	EMMC:	-
Flash:	02		
Description			
1 nmtui 2 wpa_supplicant -B -i wlan0 -c /etc/wpa_supplicant/wpa_supplicant.conf			

History

#1 - 03/12/2025 05:35 PM

\\192.168.1.250\01-Public\wilson_test\rk3399\kernel_4_4\ddr4\25_03_12

#2 - 03/13/2025 11:09 AM

- Status changed from New to Closed