

KP12C - Bug #885

FD7352Swifi

03/17/2025 09:40 AM -

Status:	New	Start date:	03/17/2025
Priority:	Urgent	Due date:	
Assignee:		% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
OS:	KP12C	OS:	Ubuntu
CPU:	RK3568	Kernel:	Linux LPA3568 5.10.198
Board:	"LPA3568M4"	APP:	-
Build number:	05	Progress:	100%
Build type:	04	Product:	FD7352S
Build variant:	04	Platform:	YT8521SC
Path:	\\192.168.1.250\01-Public\wilson_test\rk3568\kp12c\KP12C_4_1080_Ubuntu20.04_v1.0_20250117	EMMC:	-

Description
1 kp12c FD7352Swifi RTL8852wifi \\192.168.1.250\01-Public\wilson_test\rk3568\kp12c\KP12C_4_1080_Ubuntu20.04_v1.0_20250117
2 LP120_4_1080_Ubuntu20.04_v1.0_20240109 FD7352Swifi \\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250109