

# LZ210 - Bug #888

USB3.0 U HUB HUB U 2.0 1.0

03/20/2025 06:52 PM -

<b>Status:</b>	New	<b>Start date:</b>	03/20/2025
<b>Priority:</b>	High	<b>Due date:</b>	
<b>Assignee:</b>		<b>% Done:</b>	0%
<b>Category:</b>	Driver	<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>		<b>Spent time:</b>	0.00 hour
<b>OS:</b>	LZ210	<b>OS:</b>	Ubuntu
<b>CPU:</b>	RK3562	<b>Kernel:</b>	Linux RK3562 6.1.84 #2 SMP Sun Dec 29 17:59:21 CST 2024 aarch64 aarch64 aarch64 GNU/Linux
<b>Model:</b>	-	<b>APP:</b>	-
<b>Board:</b>	-	<b>Progress:</b>	100%
<b>Part:</b>	02	<b>Part:</b>	FD7352S
<b>Part:</b>	02	<b>Part:</b>	YT8521SC
<b>Path:</b>	\\192.168.1.250\01-Public\Linx\rk3562\20250321	<b>EMMC:</b>	-
<b>Description</b>			

## History

#1 - 03/21/2025 06:27 PM -

- changed from \\192.168.1.250\01-Public\rk3562\rk3562\_lkd210\_ubuntu22.04\_12\_29.img to \\192.168.1.250\01-Public\Linx\rk3562\20250321

- 1 usb3.0 host
- 2 u u
- 3 usb3.0hub usb2.0 usb3.0