

LZ201 - Bug #903

□□□□□□□□□□□□□□□□□□

03/31/2025 09:42 AM - □□

Status:	New	Start date:	03/31/2025
Priority:	Urgent	Due date:	
Assignee:	□□	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
□□:	LZ201	□□:	Ubuntu
CPU:	RK3576	□□□□:	Linux LB3576 6.1.84
□□:	-	APP□□:	-
□□/□□□□□□□□:	-	□□□□:	100%
□□□□□□□□:	02	□□□□:	FD7352S
□□/□□□□□□□□:	01	□□□□:	YT8521SC
□□□□:	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\Linux\2025_03_10	EMMC□□:	-

Description