

LB160 - Bug #980

USB3.0 3.0U 2.0

06/19/2025 11:49 AM -

Status:	New	Start date:	06/19/2025
Priority:	High	Due date:	
Assignee:	sun	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
			lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img
CPU:	RK3588		Ubuntu
			Linux LPA3588 6.1.99
			FD7352S
		EMMC	-
	01		

Description

2USB3.03.0U2.0

```
root@LPA3588:~# lsusb -t
/: Bus 05.Port 1: Dev 1, Class=root_hub, Driver=ehci-platform/1p, 480M
/: Bus 04.Port 1: Dev 1, Class=root_hub, Driver=ohci-platform/1p, 12M
/: Bus 03.Port 1: Dev 1, Class=root_hub, Driver=ohci-platform/1p, 12M
/: Bus 02.Port 1: Dev 1, Class=root_hub, Driver=ehci-platform/1p, 480M
|   Port 1: Dev 5, If 0, Class=Hub, Driver=hub/4p, 480M
|   Port 2: Dev 6, If 0, Class=Mass Storage, Driver=usb-storage, 480M
|   Port 3: Dev 7, If 0, Class=Mass Storage, Driver=usb-storage, 480M
/: Bus 01.Port 1: Dev 1, Class=root_hub, Driver=xhci-hcd/1p, 480M
root@LPA3588:~#
root@LPA3588:~#
root@LPA3588:~# lsblk
NAME            MAJ:MIN RM  SIZE RO TYPE MOUNTPOINTS
sda              8:0    1 14.3G  0 disk
└─sda1           8:1    1 14.3G  0 part /media/neardi/A2
sdb              8:16    1 245M  0 disk
└─sdb1           8:17    1 245M  0 part /media/neardi/B7
mmcblk0         179:0    0 28.9G  0 disk
├─mmcblk0p1     179:1    0   4M  0 part
├─mmcblk0p2     179:2    0   4M  0 part
├─mmcblk0p3     179:3    0  64M  0 part
├─mmcblk0p4     179:4    0 128M  0 part
├─mmcblk0p5     179:5    0  32M  0 part
├─mmcblk0p6     179:6    0  14G  0 part /
├─mmcblk0p7     179:7    0 128M  0 part /oem
└─mmcblk0p8     179:8    0 14.5G  0 part /userdata
mmcblk0boot0    179:32    0   4M  1 disk
mmcblk0boot1    179:64    0   4M  1 disk
zram0           254:0    0    0B  0 disk
root@LPA3588:~#
```

3.0U2.0U

Files

clipboard-202506191146-7kbrn.png	52.9 KB	06/19/2025	
----------------------------------	---------	------------	--