

LZ201 - Bug #991

-25°~-40° 20%

06/20/2025 02:40 PM -

Status:	New	Start date:	06/20/2025
Priority:	Urgent	Due date:	
Assignee:		% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LZ201	:	v6.10
CPU:	RK3576	APP:	-
:	LCH3576	:	<20%
/ :	02	:	FD7352S
:	02	:	YT8521SC
/ :	-	EMMC:	-
:	rk3576_ubuntu2204_20250522.img	:	-
:	Ubuntu		
Description			
-25°~40°HDMI SOKusb RK_loglog debugUboot			

History

#1 - 06/20/2025 02:49 PM -

- Description updated