

LB160 - Bug #999

BT

06/20/2025 06:23 PM -

Status:	New	Start date:	06/20/2025
Priority:	High	Due date:	
Assignee:	sun	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
CPU:	RK3588		
	01	EMMC	-

Description

```
BT
root@LPA3588:~# hciconfig
root@LPA3588:~# hciconfig
root@LPA3588:~#
root@LPA3588:~# hciconfig hci0 up
Can't get device info: No such device
root@LPA3588:~# hciconfig hci0 up
Can't get device info: No such device
root@LPA3588:~# hcitool dev
Devices:
root@LPA3588:~# hciconfig -a
root@LPA3588:~#
root@LPA3588:~# hcitool dev
Devices:
root@LPA3588:~#
root@LPA3588:~# hciconfig -a
root@LPA3588:~# hciconfig hci0 up
Can't get device info: No such device
root@LPA3588:~#
```

Files

clipboard-202506201822-nc9gi.png	33.6 KB	06/20/2025	
----------------------------------	---------	------------	--