

DQA - Issues

#	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
920	Bug	New	High	audio demo	Ubuntu	fastboot\kernel\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/03/2025 02:57 PM
917	Bug	New	High	IP	Ubuntu	fastboot\kernel\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/02/2025 06:18 PM
916	Bug	New	High	IP	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/02/2025 06:16 PM
915	Bug	New	High	nearby	Ubuntu	fastboot\kernel\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	04/08/2025 06:20 PM
913	Bug	New	High	J2600--normal	Ubuntu	fastboot\kernel\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	04/02/2025 05:29 PM
912	Bug	New	High	J2903--TP	Ubuntu	fastboot\kernel\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	04/02/2025 05:28 PM
911	Bug	New	High	J2904--30pin FPC	Ubuntu	fastboot\kernel\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	04/02/2025 05:25 PM
910	Bug	New	High		Ubuntu	fastboot\kernel\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	04/02/2025 05:18 PM
904	Bug	New	High	Nearby	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/01/2025 03:31 PM
902	Bug	New	High	camera	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/01/2025 03:36 PM
901	Bug	New	High	USB 100M ssh camera	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/01/2025 03:33 PM
900	Bug	New	High	audio demo	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	03/27/2025 05:30 PM
899	Bug	New	High	J2904--30pin FPC	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	03/27/2025 04:57 PM
898	Bug	New	High	J2903--TP	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	03/27/2025 04:46 PM
897	Bug	New	High	J2600--normal	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	sun	03/27/2025 04:42 PM
896	Bug	New	High	npu demo	Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	03/27/2025 05:35 PM
894	Bug	New	High		Ubuntu	192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	03/27/2025 04:36 PM
890	Bug	New	High	LED	Ubuntu	192.168.1.250\01-Public\Linx\rk3562\20250321		03/21/2025 06:54 PM
888	Bug	New	High	USB3.0 HUB	Ubuntu	192.168.1.250\01-Public\Linx\rk3562\20250321		03/21/2025 06:27 PM
887	Bug	New	High		Ubuntu	192.168.1.250\01-Public\rk3562\rk3562_lkd210_ubuntu22.04_12_29.img		03/20/2025 06:48 PM
886	Bug	New	High	HDMI	Android	192.168.1.250\03-image\rk3588-a12\LKD3588-\kd3588-android12-V3-fd7352s-bt-ok-20250114\lkd3588-android12-V3-fd7352s-bt-ok-20250114.img	sun	03/17/2025 09:47 AM
879	Bug	New	High	HDMI	Ubuntu	192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250314	Linx	03/14/2025 03:26 PM
874	Bug	New	High	J2904--30pin FPC	Ubuntu	192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304		03/06/2025 03:19 PM

#	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
871	Bug	New	High	Neardi	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/07/2025 05:23 PM
868	Bug	New	High		Ubuntu	-		03/04/2025 07:46 PM
867	Bug	New	High		Ubuntu	-		03/04/2025 07:44 PM
865	Bug	New	High		Ubuntu	-		03/04/2025 06:40 PM
864	Bug	New	High	U9606/U9607/U9608	Ubuntu	-		03/04/2025 06:08 PM
863	Bug	New	High	M4	Ubuntu	-		03/04/2025 05:21 PM
860	Bug	New	High	CR	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	03/04/2025 03:09 PM
857	Bug	New	High	RTC	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	03/03/2025 04:04 PM
855	Bug	New	High		Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	sun	02/28/2025 02:14 PM
851	Bug	New	High	cat /dev/ttyS3 GA BDG BDGSV	Ubuntu	ubuntu22.04_lb201_25_01_07.img		02/27/2025 06:53 PM
850	Bug	New	High	MIC	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	jing	02/28/2025 02:18 PM
849	Bug	New	High	MINI PCIe M.2	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	jing	02/27/2025 05:15 PM
847	Bug	New	High	5G	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	sun	02/28/2025 02:17 PM
845	Bug	New	High	USB3.0 HUB	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	Linx	02/27/2025 03:25 PM
844	Bug	New	High	audio demo	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	04/18/2025 06:38 PM
827	Bug	New	High	TP	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/08/2025 06:15 PM
826	Bug	New	High	MIPI DSI TX mipi	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/08/2025 06:13 PM
825	Bug	New	High	WORK	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/08/2025 11:34 AM
823	Bug	New	High	BT	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23		02/06/2025 02:57 PM
818	Bug	New	High	HDMI FPC	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/22/2025 12:00 PM
817	Bug	New	High	SIM	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/22/2025 10:56 AM
816	Bug	New	High	rootfs NetworkManager-wait-online.service	Ubuntu	ubuntu22.04_lb201_25_01_07.img	Linx	01/22/2025 11:46 AM
815	Bug	New	High	HDMI LCD HDMI	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/22/2025 10:06 AM
813	Bug	New	High	D/I GPIO55	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/21/2025 03:56 PM
812	Bug	New	High	D/O 12V	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/21/2025 10:54 AM
809	Bug	New	High	Type-C	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/16/2025 05:56 PM

#	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
808	Bug	New	High	LP120_4_1080_Ubuntu20.04_v1.0_20250110.img TF	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img		01/15/2025 05:55 PM
806	Bug	New	High					01/15/2025 03:45 PM
803	Bug	New	High	wifi				01/15/2025 03:32 PM
800	Bug	New	High	Wifi				02/06/2025 10:24 AM
792	Bug	New	High	LCD	Ubuntu	ubuntu22.04_lb201_25_01_07.img	er	01/09/2025 10:04 AM
790	Bug	New	High		Ubuntu	ubuntu22.04_lb201_25_01_07.img	er	01/08/2025 08:02 PM
789	Bug	New	High	RS485/CAN	Ubuntu	ubuntu22.04_lb201_25_01_07.img	er	01/08/2025 07:57 PM
786	Bug	New	High		Ubuntu		jing	01/08/2025 05:48 PM
782	Bug	New	High	eth1	Ubuntu	ubuntu22.04_lb201_25_01_07.img	er	02/26/2025 03:49 PM
781	Bug	New	High	DC/IN	Ubuntu	ubuntu22.04_lb201_25_01_07.img	er	01/08/2025 11:32 AM
778	Bug	New	High	AHD	Ubuntu	LP120_4_1080_Ubuntu20.04_v1.0_20240929.img		01/06/2025 09:08 PM
776	Bug	New	High	USB2.0 USB1.0	Ubuntu	LZ112_3588_ubuntu20.04_v1.0_20240204_1649		01/02/2025 02:05 PM
774	Bug	New	High	SARADC0_IN6 1.8V GND 1.3V	Ubuntu	rk3562_lkd210_ubuntu22.04_12_29.img	zenghui	01/06/2025 11:14 AM
772	Bug	New	High	WIFI/BT	Ubuntu	rk3562_lkd210_ubuntu22.04_12_29.img	KuangJie	12/30/2024 10:44 AM
771	Bug	New	High		Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/27/2024 09:06 PM
766	Bug	New	High	Ubuntu	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	12/26/2024 04:31 PM
765	Bug	New	High	CPU GPU NPU	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	01/03/2025 05:48 PM
754	Bug	New	High	USB3.0_OTG	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	01/13/2025 09:53 AM
752	Bug	New	High	FD7352S-BS AP	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	KuangJie	12/27/2024 10:25 AM
749	Bug	New	High		Ubuntu		shiliang	12/23/2024 04:05 PM
748	Bug	New	High	root gst	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	01/10/2025 10:15 AM
747	Bug	New	High		Ubuntu		shiliang	12/23/2024 02:34 PM
745	Bug	New	High		Ubuntu		shiliang	12/23/2024 02:24 PM
742	Bug	New	High	POP	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/24/2024 04:53 PM
739	Bug	New	High	LP11A				12/20/2024 06:19 PM
738	Bug	New	High	LC210 SC	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img		12/20/2024 04:24 PM
737	Bug	New	High	12V 15V 16V AHD	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	jing	01/17/2025 03:55 PM

#	Tracker	Status	Priority	Subject	OS	Image	Assignee	Updated
736	Bug	New	High	USB2.0 4Gbps	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/24/2024 04:55 PM
734	Bug	New	High	demo UI	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/07/2025 05:24 PM
731	Bug	New	High	power system	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	01/06/2025 11:18 AM
728	Bug	New	High	power	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	01/03/2025 06:52 PM
726	Bug	New	High	system LED	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	01/03/2025 06:54 PM
721	Bug	New	High		Ubuntu			02/17/2025 01:56 PM
719	Bug	New	High					02/17/2025 01:56 PM
717	Bug	New	High	thermal dmc cpufreq	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	sun	03/07/2025 02:44 PM
714	Bug	New	High	U0501 45°C	Ubuntu	https://forum.nearidi.com/d/126-hisi3403-xia-zai-gu-jian	jing	12/16/2024 06:25 PM
699	Bug	New	High	J2903--TP	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	sun	03/06/2025 03:25 PM
685	Bug	New	High	Master SSD	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/12/2024 06:53 PM
673	Bug	New	High	Onboard EXT SPK	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/12/2024 11:45 AM
669	Bug	New	High	EHT1	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/23/2024 10:31 AM
667	Bug	New	High	60s	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/11/2024 06:02 PM
665	Bug	New	High	I/O	Ubuntu	Linux_for_Tegra.tar.gz		12/11/2024 02:39 PM
663	Bug	New	High	I/O	Ubuntu	Linux_for_Tegra.tar.gz		12/11/2024 11:23 AM
662	Bug	New	High	M.2 SSD	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/11/2024 10:05 AM
638	Bug	New	High	4K	Ubuntu	Linux_for_Tegra.tar.gz	Linx	11/21/2024 10:28 AM
637	Bug	New	High	M.2 Slot M3.0	Ubuntu	Linux_for_Tegra.tar.gz	jing	11/20/2024 04:11 PM
634	Bug	New	High	wifi HE-MCS	Ubuntu	\\192.168.1.250\17-OpenImage\nearidi-download\RK3568\LPB3568\ubuntu	KuangJie	11/15/2024 05:26 PM
632	Bug	New	High	BT	Ubuntu	rk3576_lb200_ubuntu2204_12_03.img		02/21/2025 04:01 PM
620	Bug	New	High		Ubuntu	rk3576_lb200_ubuntu22.04_20241108A.img	er	12/06/2024 04:59 PM
615	Bug	New	High	4G	Ubuntu	\\192.168.1.250\17-OpenImage\nearidi-download\RK3568\LPB3568\ubuntu		01/17/2025 11:33 AM
583	Bug	New	High	4pin speaker	Ubuntu	\\192.168.1.250\17-OpenImage\nearidi-download\RK3588\LPA3588\Ubuntu	sun	10/30/2024 09:58 AM
570	Bug	New	High	mac mac IP	Ubuntu	rk3399pro_KZ117_ubuntu_gaussion_ddr3_20240628.img	Linx	11/25/2024 03:32 PM

#	Tracker	Status	Priority	Subject	OS	File Name	Assignee	Updated
553	Bug	New	High	FD7352P STA 2.4G ax-40 t x mcs 11 mcs 11 mcs	Ubuntu	update-pcie.img	KuangJie	09/12/2024 01:45 PM
552	Bug	New	High	FD7352P STA ac-80 iperf3	Ubuntu	update-pcie.img	KuangJie	09/12/2024 10:31 AM
551	Bug	New	High	AP6275S LPA3588 AP 70%	Ubuntu	update.img	sun	09/11/2024 06:42 PM
550	Bug	New	High	FD7352P, STA 2.4G n only rx ac. n ac	Ubuntu	update-pcie.img	KuangJie	09/10/2024 04:59 PM
549	Bug	New	High	FD7352P, ax80 tx 70. 800~900Mbits/sec 750 Mbits/sec	Ubuntu	update-pcie.img	KuangJie	09/12/2024 01:48 PM
517	Bug	New	High	X_Y	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240806v2.0.img		08/13/2024 03:14 PM
500	Bug	New	High	SIM	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240702v1.0.img		07/24/2024 11:50 AM
492	Bug	New	High	KD17A, iperf3 100Mbits/sec 500-600Mbits/sec	Ubuntu	KZ17A_ubuntu20.04_v1.9_fixed_fd7352s_crash_20240708.img	sun	07/17/2024 02:16 PM
482	Bug	New	High	LVDS LD166 LVDS	Ubuntu	lkd3588-t0-ubuntu-240703.img	sun	07/10/2024 04:08 PM
476	Bug	New	High	USB1_3.0U 2.0 3.0	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240702v1.0.img	shiliang	07/08/2024 06:18 PM
472	Bug	New	High	12V OUT 11.2V	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-v1.0.img	jing	07/01/2024 04:26 PM
464	Bug	New	High	M.2	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\pcie.3.0\LKD3588_ubuntu20.04_v1.0_20240523_1544.img	sun	06/14/2024 02:33 PM
439	Bug	New	High	LB120 eth1 350	Ubuntu	LBA3568_ubuntu20.04_v1.0_20240301_2020.img	Linx	03/29/2024 10:58 AM
435	Bug	New	High	KD17A AP SSID, WIFI	Ubuntu	update.img	sun	03/12/2024 03:11 PM
408	Bug	New	High	sony1.mp4 ch-test.wav	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/13/2023 11:49 AM
407	Bug	New	High	HDMI_OUT3	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/13/2023 10:06 AM
406	Bug	New	High	sony1.mp4 ch-test.wav	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/11/2023 05:46 PM
388	Feature	New	High	can 3588	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/26/2023 02:44 PM
380	Bug	New	High	RS232 --COM3 ttysWK 3	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	sun	07/10/2023 11:57 AM
372	Bug	New	High	HDMI-RX video1	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	sun	07/04/2023 11:49 AM
338	Bug	New	High		Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704	Linx	07/14/2023 10:35 AM
337	Bug	New	High		Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704		07/18/2023 04:22 PM
319	Bug	New	High	4 COM RS232	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	sun	09/18/2023 03:40 PM