

KP12C - Issues

#	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
885	Bug	New	Urgent	WiFi FD7352Swifi	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\kp12c\KP12C_4_1080_Ubuntu20.04_v1.0_20250117		03/17/2025 09:40 AM
808	Bug	New	High	LP120_4_1080_Ubuntu20.04_v1.0_20250110.img TF	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img		01/15/2025 05:55 PM
796	Bug	New	Normal	usb2.0 to usb3.0 hub 30%	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img	Linx	01/14/2025 11:54 AM
795	Bug	New	Normal	AHD	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img		01/13/2025 09:55 AM
791	Bug	New	Urgent	TF	Ubuntu	LP120_4_1080_Ubuntu20.04_v1.0_20240929.img		01/10/2025 10:33 AM
778	Bug	New	High	AHD	Ubuntu	LP120_4_1080_Ubuntu20.04_v1.0_20240929.img		01/06/2025 09:08 PM