

LB160 - Issues

#	Tracker	Status	Priority	Subject	OS	Image	Assignee	Updated
990	Bug	New	High	J4500/J4501 无法启动	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/20/2025 11:56 AM
989	Bug	New	High	GPIO 无法使用	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/20/2025 11:38 AM
987	Bug	New	High	无法通过 demo 启动	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 06:00 PM
986	Bug	New	High	无法通过 sys 启动	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 05:35 PM
985	Bug	New	High	eth1 无法使用, 速度 10M	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 04:48 PM
983	Bug	New	High	5V0 3V3 无法使用	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 04:03 PM
981	Bug	New	High	485 无法使用	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 03:06 PM
980	Bug	New	High	USB3.0 无法使用 3.0V 无法使用 2.0V	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 11:49 AM
979	Bug	New	High	无法通过 PWR 启动	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 10:45 AM