

LB160 - Issues

#	Tracker	Status	Priority	Subject	OS	Image	Assignee	Updated
999	Bug	New	High	BT module	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/20/2025 06:23 PM
998	Bug	New	High	MMC.M.2	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/20/2025 04:42 PM
997	Bug	New	High	SPK module	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/20/2025 04:29 PM
996	Bug	New	High	MIC module	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/20/2025 04:02 PM
995	Bug	New	High	GPIO	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/20/2025 03:54 PM
994	Bug	New	High	GPIO TF module	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/20/2025 03:29 PM
993	Bug	New	High	4G module	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/20/2025 03:15 PM
992	Bug	New	High	4G module Modem hangup	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/20/2025 03:08 PM
990	Bug	New	High	J4500/J4501 module	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/20/2025 11:56 AM
989	Bug	New	High	GPIO module	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/20/2025 03:31 PM
988	Bug	New	High	RTC module	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	jing	06/20/2025 10:06 AM
987	Bug	New	High	6pin demo	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 06:00 PM
986	Bug	New	High	sta sys module	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 05:35 PM
985	Bug	New	High	eth1 module, 10M	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 04:48 PM
984	Bug	New	High	eth0 module	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/20/2025 04:30 PM
983	Bug	New	High	5V0/3V3 module	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 04:03 PM
981	Bug	New	High	485 module	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 03:06 PM
980	Bug	New	High	USB3.0/3.0V module 2.0	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 11:49 AM
979	Bug	New	High	module PWR module	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	sun	06/19/2025 10:45 AM
978	Bug	New	High	module	Ubuntu	lbr3588_ubuntu22.04_linux_6.1_v1.0_20250610.img	jing	06/19/2025 10:37 AM