

LP201 - Issues

#	Tracker	Status	Priority	Subject	OS	Image	Assignee	Updated
857	Bug	New	High	RTC不工作	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	03/03/2025 04:04 PM
851	Bug	New	High	无法通过cat /dev/ttyS3查看BDGGA和BDGS版本	Ubuntu	ubuntu22.04_lb201_25_01_07.img	li	02/27/2025 06:53 PM
819	Bug	New	Normal	无法2280M.2	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/23/2025 09:52 AM
818	Bug	New	High	HDMI接口FPC不工作	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/22/2025 12:00 PM
817	Bug	New	High	无法SIM卡SIM不工作	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/22/2025 10:56 AM
816	Bug	New	High	rootfs无法启动NetworkManager-wait-online.service 27.848s	Ubuntu	ubuntu22.04_lb201_25_01_07.img	Linx	01/22/2025 11:46 AM
814	Bug	New	Normal	ubuntu debian 1080P30 1080P60 无法启动buildroot	Ubuntu	ubuntu22.04_lb201_25_01_07.img	Linx	01/21/2025 04:23 PM
813	Bug	New	High	无法通过D/I GPIO55 工作	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/21/2025 03:56 PM
812	Bug	New	High	D/O无法12V工作	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/21/2025 10:54 AM
811	Bug	New	Normal	无法reboot--SPK pop	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/22/2025 11:01 AM
809	Bug	New	High	Type-C无法工作	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/16/2025 05:56 PM
792	Bug	New	High	LCD无法工作	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/09/2025 10:04 AM
790	Bug	New	High	无法工作	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/08/2025 08:02 PM
789	Bug	New	High	RS485/CAN无法工作	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/08/2025 07:57 PM
787	Bug	New	Urgent	无法工作3-5	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/22/2025 10:42 AM
785	Bug	New	Immediate	无法工作	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/08/2025 06:19 PM
782	Bug	New	High	无法eth1工作	Ubuntu	ubuntu22.04_lb201_25_01_07.img		02/26/2025 03:49 PM
781	Bug	New	High	DC/IN无法工作	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/08/2025 11:32 AM