

LP201 - Issues

#	Tracker	Status	Priority	Subject	OS	File Name	Assignee	Updated
868	Bug	New	High	GPIO pin not working	Ubuntu	-	shiliang	03/04/2025 07:46 PM
867	Bug	New	High	GPIO pin not working	Ubuntu	-	shiliang	03/04/2025 07:44 PM
866	Bug	New	Urgent	TYPE-C/SIM not working	Ubuntu	-	shiliang	03/04/2025 06:57 PM
865	Bug	New	High	GPIO pin not working	Ubuntu	-	shiliang	03/04/2025 06:40 PM
864	Bug	New	High	U9606/U9607/U9608 not working	Ubuntu	-	shiliang	03/04/2025 06:08 PM
863	Bug	New	High	M4 not working	Ubuntu	-	shiliang	03/04/2025 05:21 PM
862	Bug	New	Normal	GPIO pin not working	Ubuntu	-	shiliang	03/04/2025 04:38 PM
860	Bug	New	High	CR not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	03/04/2025 03:09 PM
857	Bug	New	High	RTC not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	03/03/2025 04:04 PM
851	Bug	New	High	GPIO pin not working cat /dev/ttyS3 BDGGA BDGS V	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	02/27/2025 06:53 PM
819	Bug	New	Normal	GPIO pin not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/23/2025 09:52 AM
818	Bug	New	High	HDMI not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/22/2025 12:00 PM
817	Bug	New	High	SIM not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/22/2025 10:56 AM
816	Bug	New	High	rootfs not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img	Linx	01/22/2025 11:46 AM
814	Bug	New	Normal	ubuntu debian 1080P30 1080P60 buildroot	Ubuntu	ubuntu22.04_lb201_25_01_07.img	Linx	01/21/2025 04:23 PM
813	Bug	New	High	D/I GPIO55 not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/21/2025 03:56 PM
812	Bug	New	High	D/O not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/21/2025 10:54 AM
811	Bug	New	Normal	reboot--SPK not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/22/2025 11:01 AM
809	Bug	New	High	Type-C not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/16/2025 05:56 PM
792	Bug	New	High	LCD not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/09/2025 10:04 AM
790	Bug	New	High	GPIO pin not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/08/2025 08:02 PM
789	Bug	New	High	RS485/CAN not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/08/2025 07:57 PM
787	Bug	New	Urgent	GPIO pin not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/22/2025 10:42 AM
785	Bug	New	Immediate	GPIO pin not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/08/2025 06:19 PM
782	Bug	New	High	eth1 not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img		02/26/2025 03:49 PM
781	Bug	New	High	DC/IN not working	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/08/2025 11:32 AM