

Issues

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
924	LP11A	Bug	New	Normal	RS232/RS485/GPIO Vcc_Out 00001A00000000000000	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\00\v03	jing	04/25/2025 02:10 PM
919	LZ750	Bug	New	Urgent	gpio500000	Ubuntu	fastboot\kernel\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	04/03/2025 02:43 PM
910	LZ750	Bug	New	High	000000	Ubuntu	fastboot\kernel\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	04/02/2025 05:18 PM
895	LZ700(LD700)	Bug	New	Urgent	0000PCIE0000000000M.200	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	03/27/2025 04:36 PM
894	LZ700(LD700)	Bug	New	High	000000	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	03/27/2025 04:36 PM
893	LZ700(LD700)	Bug	New	Urgent	0000001000M00000	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	jing	03/27/2025 04:36 PM
892	LB700	Bug	Closed	High	LZ700(LD70086401)--000000	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-sup port-UI-20250314	jing	03/27/2025 03:54 PM
891	LB700	Bug	Closed	Urgent	LZ700(LD70086401)--0000001000M 000000	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-sup port-UI-20250314	jing	03/27/2025 03:52 PM
856	LZ750	Bug	Closed	High	MIPI LCD 0 Touch Screen Slot0000	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	jing	04/02/2025 05:30 PM
850	LZ750	Bug	New	High	MIC0000000000MIC0000000000 00000000	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	jing	02/28/2025 02:18 PM
849	LZ750	Bug	New	High	0000MINI PCIE000000M.2000	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	jing	02/27/2025 05:15 PM
848	LZ750	Bug	New	Urgent	0000PCIE00/00000	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	jing	02/27/2025 04:25 PM
834	LZ201	Bug	New	Normal	00HDMI0HDMI0SPK0000	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/14/2025 02:42 PM
832	LZ201	Bug	New	Normal	SPK0000000000000000	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/13/2025 01:51 PM
831	LZ201	Bug	New	Normal	0000000000000000pop0/0000rebo ot0000	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/13/2025 01:46 PM
827	LZ201	Bug	New	High	TP000000000000	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/08/2025 06:15 PM
826	LZ201	Bug	New	High	MIPI DSI TX mipi000000000000	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/08/2025 06:13 PM
825	LZ201	Bug	New	High	00WORK00000000000000000000 000000	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/08/2025 11:34 AM
824	LZ201	Bug	New	Normal	0000eth00000LED0000	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/06/2025 03:25 PM
786	LZ130	Bug	New	High	00000000	Ubuntu		jing	01/08/2025 05:48 PM
737	LP160	Bug	New	High	0000000012v0000000024v00000000 000000 015v016v0000AHD00000000	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	jing	01/17/2025 03:55 PM

#	Project	Tracker	Status	Priority	Subject	OS	Link	Assignee	Updated
714	LB700	Bug	New	High	U0501温度传感器45°C	Ubuntu	https://forum.nearidi.com/d/126-hisi3403-xia-zai-gu-jian	jing	12/16/2024 06:25 PM
713	LP620	Bug	New	Urgent	USB/Type-C 无法识别	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/13/2024 09:18 PM
711	LP620	Bug	New	Normal	MCP2515 CAN2&3 无法通信	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/13/2024 08:13 PM
710	LP620	Bug	New	Urgent	RS485 ttyWK0/ttyWK1 无法通信	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/13/2024 07:55 PM
709	LP620	Bug	New	Normal	J3304/J3303 RS485 AB 无法通信	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/13/2024 07:49 PM
691	LB700	Bug	Closed	High	Mini-PCIE 无法识别	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	jing	03/14/2025 03:21 PM
687	LB700	Bug	Closed	High	PCBA 无法识别	Ubuntu	https://forum.nearidi.com/d/126-hisi3403-xia-zai-gu-jian	jing	04/17/2025 03:28 PM
674	LP620	Bug	New	Normal	TF 无法识别	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/12/2024 01:49 PM
666	LP620	Bug	New	Urgent	EC20 USB3.0 I/O 无法识别	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/11/2024 04:51 PM
662	LP620	Bug	New	High	M.2 SSD 无法识别	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/11/2024 10:05 AM
658	LP620	Bug	New	Normal	无法识别	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/10/2024 03:06 PM
657	LP620	Bug	New	Normal	RTC 无法识别	Ubuntu	Linux_for_Tegra.tar.gz	jing	12/10/2024 02:48 PM
642	LP160	Bug	New	Normal	A/I 无法识别	Ubuntu	\\192.168.1.250\17-OpenImage\nearidi-download\RK3588\LPA3588\Ubuntu	jing	01/14/2025 05:51 PM
639	LP620	Bug	New	Urgent	J3300 12V 无法识别 4.84 无法识别	Ubuntu	Linux_for_Tegra.tar.gz	jing	11/21/2024 04:20 PM
637	LP620	Bug	New	High	M.2 Slot M3.0 无法识别	Ubuntu	Linux_for_Tegra.tar.gz	jing	11/20/2024 04:11 PM
636	LP620	Bug	New	Immediate	PCIe3.0 SSD 无法识别	Ubuntu	Linux_for_Tegra.tar.gz	jing	11/20/2024 03:53 PM
609	LP122	Bug	New	Urgent	HDMI2 无法识别 HDMI 无法识别	Ubuntu	\\192.168.1.250\17-OpenImage\nearidi-download\RK3568\LPB3568\ubuntu	jing	11/15/2024 04:34 PM
604	LPM3568	Bug	Closed	Normal	can1 1000k 无法识别	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	jing	11/11/2024 02:45 PM
602	LPM3568	Bug	Closed	Low	eth 无法识别	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	jing	11/11/2024 11:23 AM
601	LPM3568	Bug	New	Normal	USB2.0 USB3.0 无法识别	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	jing	11/08/2024 11:41 AM
600	LPM3568	Feature	New	Normal	USB 无法识别	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	jing	11/08/2024 11:55 AM
596	LPM3568	Bug	Closed	Normal	USB 无法识别	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	jing	11/07/2024 04:07 PM
587	LP160	Bug	New	Urgent	16v AHD 无法识别	Ubuntu	\\192.168.1.250\17-OpenImage\nearidi-download\RK3588\LPA3588\Ubuntu	jing	04/15/2025 05:03 PM
576	LP120	Feature	New	Urgent	FPGA 无法识别	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568	jing	01/17/2025 02:06 PM
574	LP120	Bug	Closed	Normal	UBS3 USB4 USB HDMI 无法识别	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\LP120_Ubuntu20.04_v1.0_20240929	jing	01/17/2025 11:28 AM
563	LP122	Bug	Closed	Urgent	85°C sysbench 无法识别	Ubuntu	\\192.168.1.250\17-OpenImage\nearidi-download\RK3568\LPB3568\ubuntu\L PB3568_ubuntu20.04_HDMI_v1.0_20240524_1358	jing	10/29/2024 09:37 AM
561	LP122	Bug	Closed	Urgent	70°C HDMI 无法识别	Ubuntu	\\192.168.1.250\17-OpenImage\nearidi-download\RK3568\LPB3568\ubuntu\L PB3568_ubuntu20.04_HDMI_v1.0_20240524_1358	jing	01/17/2025 11:33 AM
560	LP11A	Bug	Closed	High	Maskrom 无法识别 ID B 无法识别	Ubuntu	LP11A_3399pro_ubuntu_test_v1.0_20240726.img	jing	09/19/2024 05:16 PM

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
559	LP122	Bug	Closed	Urgent	85°C 100% USB 100%	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu\L PB3568_ubuntu20.04_HDMI_v1.0_20240524_1358	jing	10/29/2024 09:37 AM
542	LP120	Bug	Closed	Normal	A/I port 1023	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568	jing	10/09/2024 11:10 AM
535	LP120	Feature	New	Normal	100% 100% 100%	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568	jing	10/23/2024 04:31 PM
524	LP120	Bug	Closed	High	USB2.0 100% 100%	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568	jing	01/17/2025 11:28 AM
523	LP120	Bug	Closed	High	USB3.0 100% 100% <4V)	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568	jing	01/17/2025 11:28 AM
516	LP11A	Feature	Closed	High	L0302 100%		-	jing	11/07/2024 02:07 PM
513	LP11A	Bug	Closed	High	U2505 100%		-	jing	08/22/2024 02:48 PM
512	LP11A	Bug	Closed	Urgent	U2505 100%		-	jing	08/22/2024 02:48 PM
506	LP11A	Feature	Closed	Normal	100% 100% 100% USB 100% 100% MaskR om	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V3.0\update.im g	jing	08/14/2024 10:50 AM
505	LP11A	Bug	Closed	Urgent	RS485 100% 100%	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V3.0\update.im g	jing	08/21/2024 01:54 PM
499	LP11A	Feature	Closed	Urgent	L2700 100%		-	jing	08/21/2024 02:08 PM
489	KD17A	Bug	New	Urgent	100% 100% 100% 100% sdio 100%	Ubuntu	KZ17A_ubuntu20.04_v1.8_yt8521_driver_strength_20240704.img	jing	07/16/2024 11:05 AM
488	LP11A	Bug	Closed	Urgent	SPK 100% 100% 100%	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V3.1\update.im g	jing	07/18/2024 03:44 PM
485	LP11A	Bug	Closed	Low	100% U0902 100% 79°+		-	jing	01/02/2025 04:11 PM
484	LP11A	Bug	Closed	Urgent	100% U0600 100% 80°+		-	jing	07/23/2024 11:03 PM
479	LP11A	Bug	Closed	Urgent	U0103 100% 100°+		-	jing	07/23/2024 10:54 PM
478	LP11A	Bug	Closed	Normal	D2700 100% 75°+		-	jing	07/23/2024 10:51 PM
477	LP11A	Bug	Closed	Urgent	9V 100% Full I/O & Sys Stress Test 100%	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V2.0\update.im g	jing	07/15/2024 09:09 PM
475	LP11A	Bug	Closed	Normal	100% 100% 100%		-	jing	08/15/2024 02:45 PM
472	KD16C(100%)	Bug	New	High	12V OUT 100% 11.2V 100%	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-v1.0.img	jing	07/01/2024 04:26 PM
469	LP11A	Bug	Closed	Normal	LD11A 100% 100% 100%		-	jing	08/14/2024 03:14 PM
466	LP11A	Bug	Closed	High	LP11A I/O 100% PIN 100% 100%		-	jing	08/21/2024 02:08 PM
465	LP11A	Bug	Closed	Normal	LP11A I/O 100% 100%		-	jing	08/15/2024 02:49 PM
462	LP11A	Bug	Closed	Urgent	3PIN LCD 100% 100%		\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V1.0\update.im g	jing	07/09/2024 01:46 PM
449	LP11A	Bug	Closed	Normal	LD11A 02 PWR 100%	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\update.img	jing	08/14/2024 03:31 PM
446	LP11A	Bug	Closed	Normal	LP11A 100% 100% 100% 100% 100% 100% 100%		-	jing	08/14/2024 03:31 PM

#	Project	Tracker	Status	Priority	Subject	OS	File Name	Assignee	Updated
442	LP11A	Bug	Closed	Normal	LD11A 02 0000000000000000		-	jing	08/14/2024 03:32 PM
433	00PX30	Bug	New	Normal	KB19B 000000000000000000000000		-	jing	11/14/2023 09:28 PM
428	LP122	Bug	Closed	High	00LD120000000LJ120_04000000 00000000	Ubuntu		jing	10/31/2023 02:16 PM
422	00PX30	Bug	New	Normal	ADB00000	Android	update-android-v8.0.1.img	jing	10/20/2023 12:53 PM
416	LP11A	Bug	Closed	Urgent	LD11A 01 000000000000000000		-	jing	10/09/2023 07:21 PM
414	LP11A	Bug	Closed	Normal	000000000000		-	jing	07/09/2024 01:50 PM
374	LP122	Bug	Closed	Normal	0000CTL1/20CTL3/400000000000 0gpio000000000000	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	jing	07/20/2023 06:11 PM
279	LP162	Bug	Closed	Immediate	9V000000000000	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	jing	09/18/2023 10:38 AM