

## Issues

| #   | Project      | Tracker | Status | Priority | Subject                | OS        | Path                                                                                                                                           | Assignee | Updated             |
|-----|--------------|---------|--------|----------|------------------------|-----------|------------------------------------------------------------------------------------------------------------------------------------------------|----------|---------------------|
| 927 | LZ230        | Bug     | New    | High     | USB不识别                 | Buildroot | 01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot                                                                                       | Linx     | 04/30/2025 05:38 PM |
| 923 | LZ210        | Bug     | New    | Urgent   | RK3562J sudo -i无法登录cpu | Ubuntu    | rk3562_ubuntu2204_20250409A.img                                                                                                                | Linx     | 05/09/2025 01:49 PM |
| 920 | LZ750        | Bug     | New    | High     | 音频demo无法播放             | Ubuntu    | fastboot\kernel\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326 | Linx     | 04/03/2025 02:57 PM |
| 917 | LZ750        | Bug     | New    | High     | 无法播放IP                 | Ubuntu    | fastboot\kernel\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326 | Linx     | 04/02/2025 06:18 PM |
| 916 | LZ700(LD700) | Bug     | New    | High     | 无法播放IP                 | Ubuntu    | 192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326                                                                                            | Linx     | 04/02/2025 06:16 PM |
| 909 | LZ750        | Bug     | New    | Urgent   | ddr无法读写                | Ubuntu    | fastboot\kernel\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326 | Linx     | 04/02/2025 05:38 PM |
| 907 | LZ210        | Bug     | New    | Urgent   | usb3.0hub无法识别设备        | Ubuntu    | 192.168.1.250\01-Public\Linx\rk3562\20250321                                                                                                   | Linx     | 04/01/2025 09:46 AM |
| 904 | LZ700(LD700) | Bug     | New    | High     | 无法播放Neardi             |           | 192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326                                                                                            | Linx     | 04/01/2025 03:31 PM |
| 902 | LZ700(LD700) | Bug     | New    | High     | camera无法识别设备           | Ubuntu    | 192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326                                                                                            | Linx     | 04/01/2025 03:36 PM |
| 901 | LZ700(LD700) | Bug     | New    | High     | USB100Mssh无法连接camera   | Ubuntu    | 192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326                                                                                            | Linx     | 04/01/2025 03:33 PM |
| 900 | LZ700(LD700) | Bug     | New    | High     | 音频demo无法播放audio        | Ubuntu    | 192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326                                                                                            | Linx     | 03/27/2025 05:30 PM |
| 896 | LZ700(LD700) | Bug     | New    | High     | npudemo无法播放NPU         | Ubuntu    | 192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326                                                                                            | Linx     | 03/27/2025 05:35 PM |
| 879 | LB700        | Bug     | New    | High     | 无法识别HDMI               | Ubuntu    | 192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250314                                                           | Linx     | 03/14/2025 03:26 PM |
| 872 | LB700        | Bug     | New    | Normal   | camera无法识别demo         | Ubuntu    | 192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304                                                           | Linx     | 04/18/2025 06:37 PM |
| 871 | LB700        | Bug     | New    | High     | 无法播放Neardi             | Ubuntu    | 192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304                                                           | Linx     | 03/07/2025 05:23 PM |
| 854 | LZ750        | Bug     | New    | Normal   | 无法播放                   | Ubuntu    | 192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225                                                                            | Linx     | 02/28/2025 02:23 PM |
| 845 | LB200        | Bug     | New    | High     | USB3.0HUB无法识别设备        | Ubuntu    | 192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img                                      | Linx     | 02/27/2025 03:25 PM |
| 844 | LB700        | Bug     | New    | High     | audiodemo无法播放audio     | Ubuntu    | 192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304                                                           | Linx     | 04/18/2025 06:38 PM |
| 840 | LB200        | Bug     | New    | Normal   | mmcblk0无法识别mmcblk1     | Ubuntu    | 192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img                                      | Linx     | 02/18/2025 05:20 PM |

| #   | Project | Tracker | Status | Priority | Subject                                                               | OS     | Path                                                                                                                           | Assignee | Updated             |
|-----|---------|---------|--------|----------|-----------------------------------------------------------------------|--------|--------------------------------------------------------------------------------------------------------------------------------|----------|---------------------|
| 836 | LB200   | Bug     | New    | Normal   | usb2.0 to usb3.0 hub 30% throughput                                   |        | \\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img                    | Linx     | 02/17/2025 03:31 PM |
| 833 | LZ201   | Bug     | New    | Normal   | 4g ethernet port not working 4g DNS not working                       | Ubuntu | \\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23                                                                  | Linx     | 02/13/2025 05:58 PM |
| 829 | LZ201   | Bug     | New    | Normal   | HDMI type-c to DP HDMI not working                                    | Ubuntu | \\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23                                                                  | Linx     | 02/10/2025 02:08 PM |
| 828 | LZ201   | Bug     | New    | Low      | 4.78GB to 4GB                                                         | Ubuntu | \\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23                                                                  | Linx     | 02/10/2025 04:08 PM |
| 822 | LZ201   | Bug     | New    | Normal   | rootfs not booting gst-launch-1.0 not working                         | Ubuntu | \\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23                                                                  | Linx     | 02/06/2025 02:00 PM |
| 821 | LZ201   | Bug     | New    | Urgent   | MIPI not working 3A not working                                       | Ubuntu | \\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23                                                                  | Linx     | 02/06/2025 01:40 PM |
| 816 | LP201   | Bug     | New    | High     | rootfs not booting NetworkManager-wait-online.service 27.848s         | Ubuntu | ubuntu22.04_lb201_25_01_07.img                                                                                                 | Linx     | 01/22/2025 11:46 AM |
| 814 | LP201   | Bug     | New    | Normal   | ubuntu to debian 1080P30 to 1080P60 not working buildroot not working | Ubuntu | ubuntu22.04_lb201_25_01_07.img                                                                                                 | Linx     | 01/21/2025 04:23 PM |
| 796 | KP12C   | Bug     | New    | Normal   | usb2.0 to usb3.0 hub 30% throughput                                   | Ubuntu | \\192.168.1.250\01-Public\wilson_test\rk3568\lp120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img | Linx     | 01/14/2025 11:54 AM |
| 775 | LPM3568 | Bug     | New    | Normal   | ETH not working ifconfig not working                                  | Ubuntu | \\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test                                                                        | Linx     | 12/31/2024 03:39 PM |
| 766 | LZ210   | Bug     | New    | High     | Ubuntu not booting -- not booting                                     | Ubuntu | rk3562_lkd210_ubuntu22.04_12_13.img                                                                                            | Linx     | 12/26/2024 04:31 PM |
| 763 | LZ210   | Bug     | New    | Normal   | 4k not working                                                        | Ubuntu | rk3562_lkd210_ubuntu22.04_12_13.img                                                                                            | Linx     | 12/25/2024 08:18 PM |
| 748 | LZ210   | Bug     | New    | High     | rootfs not booting gst not working                                    | Ubuntu | rk3562_lkd210_ubuntu22.04_12_13.img                                                                                            | Linx     | 01/10/2025 10:15 AM |
| 743 | LZ210   | Bug     | New    | High     | MIPI not working 3A not working                                       | Ubuntu | rk3562_lkd210_ubuntu22.04_12_13.img                                                                                            | Linx     | 05/09/2025 01:57 PM |
| 734 | LB700   | Bug     | New    | High     | demo not working UI not working                                       | Ubuntu | \\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304                                         | Linx     | 03/07/2025 05:24 PM |
| 733 | LZ210   | Bug     | New    | Normal   | not booting not booting not booting                                   | Ubuntu | rk3562_lkd210_ubuntu22.04_12_13.img                                                                                            | Linx     | 05/12/2025 06:45 PM |
| 694 | LP620   | Bug     | New    | Normal   | 4G not working quectel-CM not working                                 | Ubuntu | Linux_for_Tegra.tar.gz                                                                                                         | Linx     | 12/13/2024 02:05 PM |
| 664 | LP620   | Bug     | New    | Normal   | not working exfat not working                                         | Ubuntu | Linux_for_Tegra.tar.gz                                                                                                         | Linx     | 12/11/2024 11:23 AM |
| 638 | LP620   | Bug     | New    | High     | 4K not working                                                        | Ubuntu | Linux_for_Tegra.tar.gz                                                                                                         | Linx     | 11/21/2024 10:28 AM |

| #   | Project | Tracker | Status | Priority | Subject                                                        | OS     | Path                                                               | Assignee | Updated             |
|-----|---------|---------|--------|----------|----------------------------------------------------------------|--------|--------------------------------------------------------------------|----------|---------------------|
| 607 | LPM3568 | Bug     | New    | Normal   | 无法播放视频                                                         | Ubuntu | \\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test            | Linx     | 11/08/2024 06:40 PM |
| 605 | LPM3568 | Bug     | New    | Normal   | 无法播放HDMI视频                                                     | Ubuntu | \\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test            | Linx     | 11/29/2024 10:09 AM |
| 597 | LPM3568 | Bug     | New    | Normal   | emmc无法写入数据                                                     | Ubuntu | \\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test            | Linx     | 11/07/2024 04:07 PM |
| 585 | LP160   | Bug     | New    | Urgent   | HDMI无法播放                                                       | Ubuntu | \\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu | Linx     | 01/14/2025 05:50 PM |
| 584 | LP160   | Bug     | New    | Normal   | M.2 SSD无法写入                                                    | Ubuntu | \\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu | Linx     | 01/15/2025 11:23 AM |
| 582 | LP160   | Bug     | New    | Normal   | 无法播放TF卡视频                                                      | Ubuntu | \\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu | Linx     | 01/14/2025 06:30 PM |
| 570 | KZ117   | Bug     | New    | High     | mac无法识别mac地址IP地址                                               | Ubuntu | rk3399pro_KZ117_ubuntu_gaussian_ddr3_20240628.img                  | Linx     | 11/25/2024 03:32 PM |
| 494 | LP11A   | Feature | New    | Low      | -20度无法启动4K AHD_KP11A                                           | Ubuntu | \\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V3.2  | Linx     | 11/07/2024 02:05 PM |
| 486 | LP160   | Bug     | New    | Normal   | LKD3588_Debian_U无法启动                                           | Debian |                                                                    | Linx     | 07/15/2024 07:06 PM |
| 439 | LB120   | Bug     | New    | High     | LB120无法识别eth1地址350                                             | Ubuntu | LBA3568_ubuntu20.04_v1.0_20240301_2020.img                         | Linx     | 03/29/2024 10:58 AM |
| 434 | LP122   | Bug     | New    | Urgent   | 5G(RM500U-CNV)无法启动                                             | Ubuntu | LZ120_3568_ubuntu20.04_v1.0_20230801_1621.img                      | Linx     | 09/25/2024 04:23 PM |
| 419 | LP160   | Bug     | New    | Urgent   | 3588无法启动40-50ms无法启动100ms                                       | Ubuntu |                                                                    | Linx     | 10/16/2023 11:27 AM |
| 376 | LP122   | Bug     | New    | Normal   | /rockchip-test/np2rknn_demo.sh npu_freq_scaling.sh无法运行         | Ubuntu | LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img                      | Linx     | 11/14/2023 04:02 PM |
| 366 | LP122   | Bug     | New    | Normal   | UnixBenchGImark2-es2Stream无法运行                                 | Ubuntu | LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img                      | Linx     | 11/14/2023 03:26 PM |
| 339 | LP112   | Bug     | New    | Normal   | 无法启动                                                           | Ubuntu | lz112_3399pro_ubuntu18.04_v1.0_20230612_1704                       | Linx     | 07/18/2023 04:25 PM |
| 338 | LP112   | Bug     | New    | High     | 无法启动                                                           | Ubuntu | lz112_3399pro_ubuntu18.04_v1.0_20230612_1704                       | Linx     | 07/14/2023 10:35 AM |
| 330 | LP162   | Bug     | New    | Normal   | 无法启动Connection FailedProtocol not available.                   | Ubuntu | LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img                   | Linx     | 09/11/2023 03:49 PM |
| 327 | LP162   | Bug     | New    | Normal   | 无法播放“mpv Media Player”8k.mp4                                   | Ubuntu | LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img                   | Linx     | 09/11/2023 03:57 PM |
| 326 | LP162   | Bug     | New    | Normal   | 无法播放“mpv Media Player”jellyfish-140-mbps-4k-uhd-hevc-10bit.mkv | Ubuntu | LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img                   | Linx     | 09/11/2023 03:58 PM |

| #   | Project | Tracker | Status | Priority | Subject                                          | OS     | Image Name                                       | Assignee | Updated             |
|-----|---------|---------|--------|----------|--------------------------------------------------|--------|--------------------------------------------------|----------|---------------------|
| 323 | LP162   | Bug     | New    | Normal   | 2.03.0ubuntu20.04.1 LTS ext4 filesystem image    | Ubuntu | LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img | Linx     | 09/11/2023 03:29 PM |
| 286 | LP160   | Bug     | New    | Normal   | LPA3588_Ubuntu 20.04.5 LTS 4k8K filesystem image | Ubuntu | LP160XXX03_FT_UBUNTU_F6_V1_230509.img            | Linx     | 06/06/2023 11:39 AM |
| 280 | LP112   | Bug     | New    | Normal   | filesystem image                                 | Ubuntu | update_add_hosts_changelog.img                   | Linx     | 05/17/2023 07:54 PM |