

Issues

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
927	LZ230	Bug	New	High	USB boot	Buildroot	01-Public\wilson_test\rk3506\BGA_EMMC\25_04_23_buildroot	Linx	04/30/2025 05:38 PM
923	LZ210	Bug	New	Urgent	RK3562J sudo -i cpu	Ubuntu	rk3562_ubuntu2204_20250409A.img	Linx	05/09/2025 01:49 PM
920	LZ750	Bug	New	High	audio demo	Ubuntu	fastboot kernel \\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs \\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/03/2025 02:57 PM
917	LZ750	Bug	New	High	ip	Ubuntu	fastboot kernel \\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs \\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/02/2025 06:18 PM
916	LZ700(LD700)	Bug	New	High	ip	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/02/2025 06:16 PM
909	LZ750	Bug	New	Urgent	ddr	Ubuntu	fastboot kernel \\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225 rootfs \\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/02/2025 05:38 PM
907	LZ210	Bug	New	Urgent	usb3.0hub U	Ubuntu	\\192.168.1.250\01-Public\Linx\rk3562\20250321	Linx	04/01/2025 09:46 AM
906	LB700	Bug	Closed	Urgent	ddr	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	04/17/2025 02:30 PM
904	LZ700(LD700)	Bug	New	High	Neardi		\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/01/2025 03:31 PM
902	LZ700(LD700)	Bug	New	High	camera	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/01/2025 03:36 PM
901	LZ700(LD700)	Bug	New	High	USB 100M ssh camera	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	04/01/2025 03:33 PM
900	LZ700(LD700)	Bug	New	High	audio demo	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	03/27/2025 05:30 PM
896	LZ700(LD700)	Bug	New	High	npu demo	Ubuntu	\\192.168.1.250\01-Public\Linx\hi3403\ubuntu\20250326	Linx	03/27/2025 05:35 PM
889	LZ210	Bug	Closed	High	usb2.0 usb3.0	Ubuntu	\\192.168.1.250\01-Public\Linx\rk3562\20250321	Linx	03/31/2025 05:17 PM
879	LB700	Bug	New	High	HDMI	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250314	Linx	03/14/2025 03:26 PM
878	LB700	Bug	Closed	High	gst-launch-1.0	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/14/2025 10:34 AM
876	LB700	Bug	Closed	High	ip	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	04/17/2025 02:30 PM
875	LB700	Bug	Closed	Normal	USB root neardi	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/07/2025 11:03 AM
872	LB700	Bug	New	Normal	camera demo	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	04/18/2025 06:37 PM

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
871	LB700	Bug	New	High	Neard	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/07/2025 05:23 PM
870	LZ201	Bug	Closed	Urgent	ubuntu sync emmc	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\Linux\2025-01-23	Linx	05/19/2025 10:35 AM
869	LB700	Bug	Closed	Urgent			\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/14/2025 02:25 PM
861	LB700	Bug	Closed	Urgent	Out of memoryUnable to handle kernel		\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/06/2025 10:38 AM
859	LB700	Bug	Closed	High	kill log		\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/06/2025 10:37 AM
858	LB700	Bug	Closed	High			\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/05/2025 10:27 AM
854	LZ750	Bug	New	Normal		Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	Linx	02/28/2025 02:23 PM
846	LB200	Bug	Closed	Urgent	Ubuntu 12	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2025_02_27\rk3576_lb200_ubuntu2204_25_02_27.img	Linx	02/27/2025 06:00 PM
845	LB200	Bug	New	High	USB3.0 HUB	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	Linx	02/27/2025 03:25 PM
844	LB700	Bug	New	High	audio demo audio	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	04/18/2025 06:38 PM
843	LB700	Bug	Closed	High	camera J3504	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/06/2025 01:53 PM
842	LB700	Bug	Closed	Urgent	camera	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250314	Linx	04/18/2025 06:35 PM
841	LB700	Bug	Closed	Immediate	rootfs_20250219A	Ubuntu	\\192.168.1.250\01-Public\Linux\hi3403\ubuntu	Linx	03/06/2025 03:13 PM
840	LB200	Bug	New	Normal	mmcbld mmcbld1	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	Linx	02/18/2025 05:20 PM
836	LB200	Bug	New	Normal			\\192.168.1.250\01-Public\wilson_test\rk3576\lb200\ubuntu\emmc\2024_12_03\rk3576_lb200_ubuntu2204_12_03.img	Linx	02/17/2025 03:31 PM
833	LZ201	Bug	New	Normal	4g eth0 4g DNS	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	Linx	02/13/2025 05:58 PM
829	LZ201	Bug	New	Normal	HDMI type-c DP HDMI	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	Linx	02/10/2025 02:08 PM
828	LZ201	Bug	New	Low	4.78GB 4GB	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	Linx	02/10/2025 04:08 PM
822	LZ201	Bug	New	Normal	root gst-launch-1.0	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	Linx	02/06/2025 02:00 PM

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
821	LZ201	Bug	New	Urgent	MIPI 3A	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	Linx	02/06/2025 01:40 PM
816	LP201	Bug	New	High	rootfs NetworkManager-wait-on line.service 27.848s	Ubuntu	ubuntu22.04_lb201_25_01_07.img	Linx	01/22/2025 11:46 AM
814	LP201	Bug	New	Normal	ubuntu debian 1080P30 1080P60 buildroot	Ubuntu	ubuntu22.04_lb201_25_01_07.img	Linx	01/21/2025 04:23 PM
796	KP12C	Bug	New	Normal	usb2.0 usb3.0 hub 30%	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img	Linx	01/14/2025 11:54 AM
794	KP12C	Bug	Closed	High	exfat	Ubuntu	LP120_4_1080_Ubuntu20.04_v1.0_20240109.img	Linx	01/10/2025 09:53 PM
777	LZ130	Bug	Closed	Normal	-20°C	Ubuntu		Linx	01/15/2025 11:50 AM
775	LPM3568	Bug	New	Normal	ETH ifconfig	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	Linx	12/31/2024 03:39 PM
766	LZ210	Bug	New	High	Ubuntu --	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	12/26/2024 04:31 PM
763	LZ210	Bug	New	Normal	4k	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	12/25/2024 08:18 PM
748	LZ210	Bug	New	High	root gst	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	01/10/2025 10:15 AM
743	LZ210	Bug	New	High	MIPI 3A	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	05/09/2025 01:57 PM
734	LB700	Bug	New	High	demo UI	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/07/2025 05:24 PM
733	LZ210	Bug	New	Normal		Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	05/12/2025 06:45 PM
716	LB700	Bug	Closed	High	NPU	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	04/17/2025 03:27 PM
697	LB700	Bug	Closed	Normal	TF	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/06/2025 02:19 PM
696	LB700	Bug	Closed	Normal	U	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/06/2025 02:28 PM
694	LP620	Bug	New	Normal	4G quectel-CM	Ubuntu	Linux_for_Tegra.tar.gz	Linx	12/13/2024 02:05 PM
692	LB700	Bug	Closed	Normal	MobaXterm SSH	Ubuntu	https://forum.neardi.com/d/126-hisi3403-xia-zai-gu-jian	Linx	12/25/2024 10:45 AM
688	LB700	Bug	Closed	Low	(reboot) log	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	03/07/2025 02:52 PM

#	Project	Tracker	Status	Priority	Subject	OS	Details	Assignee	Updated
664	LP620	Bug	New	Normal	exfat	Ubuntu	Linux_for_Tegra.tar.gz	Linx	12/11/2024 11:23 AM
652	LZ130	Bug	Closed	Normal	Unix Bench	Ubuntu		Linx	02/17/2025 05:29 PM
646	LZ130	Bug	Closed	Normal	HDMI	Ubuntu		Linx	02/17/2025 05:25 PM
641	LPM3568	Bug	Closed	Normal		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	Linx	11/26/2024 10:49 AM
638	LP620	Bug	New	High	4K	Ubuntu	Linux_for_Tegra.tar.gz	Linx	11/21/2024 10:28 AM
629	LPM3568	Bug	Closed	Urgent	eh10mac	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	Linx	11/25/2024 02:24 PM
621	LB200	Bug	Closed	Urgent	HDMI		\\192.168.1.250\01-Public\wilson_test\rk3576\ubuntu\2024_11_11\rk3576_lb200_ubuntu2204_11_11.img	Linx	12/03/2024 02:42 PM
617	LP122	Bug	Closed	Normal	4G PPP ping	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu	Linx	11/13/2024 07:20 PM
612	LB200	Bug	Closed	High	IP	Ubuntu	rk3576_lb200_ubuntu22.04_20241108A.img	Linx	12/03/2024 02:18 PM
610	LB200	Bug	Closed	High		Ubuntu	rk3576_lb200_ubuntu2204_12_03.img	Linx	12/03/2024 02:12 PM
607	LPM3568	Bug	New	Normal		Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	Linx	11/08/2024 06:40 PM
605	LPM3568	Bug	New	Normal	HDMI	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	Linx	11/29/2024 10:09 AM
597	LPM3568	Bug	New	Normal	emmc	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	Linx	11/07/2024 04:07 PM
586	LP160	Bug	Closed	Normal			\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	Linx	01/14/2025 06:13 PM
585	LP160	Bug	New	Urgent	HDMI	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	Linx	01/14/2025 05:50 PM
584	LP160	Bug	New	Normal	M.2 SSD	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	Linx	01/15/2025 11:23 AM
582	LP160	Bug	New	Normal	TF	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LPA3588\Ubuntu	Linx	01/14/2025 06:30 PM
577	LP11A	Bug	Closed	High			\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V1.0\update.img	Linx	11/07/2024 02:00 PM
575	LP120	Bug	Closed	High	HDMI	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lp3568	Linx	10/14/2024 03:21 PM

#	Project	Tracker	Status	Priority	Subject	OS	File Path	Assignee	Updated
570	KZ117	Bug	New	High	mac reboot mac reboot IP reboot	Ubuntu	rk3399pro_KZ117_ubuntu_gaussion_ddr3_20240628.img	Linx	11/25/2024 03:32 PM
564	LP122	Bug	Closed	Urgent	85°C reboot	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu\LPB3568_ubuntu20.04_HDMI_v1.0_20240524_1358	Linx	10/29/2024 09:36 AM
557	LP122	Bug	Closed	Normal	-40°C reboot wifi	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu\LPB3568_ubuntu20.04_HDMI_v1.0_20240524_1358	Linx	01/15/2025 09:51 AM
545	LP120	Bug	Closed	High	HDMI reboot	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568	Linx	10/12/2024 04:35 PM
532	LP120	Bug	Closed	Low	reboot	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568	Linx	10/14/2024 03:23 PM
531	LP120	Feature	Closed	Normal	reboot	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568	Linx	01/14/2025 09:58 AM
522	LP120	Bug	Closed	Normal	nmtui reboot	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568	Linx	09/06/2024 04:15 PM
509	LP11A	Bug	Closed	High	AHD reboot	Ubuntu		Linx	08/15/2024 02:30 PM
494	LP11A	Feature	New	Low	-20°C reboot AHD_KP11A	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V3.2	Linx	11/07/2024 02:05 PM
486	LP160	Bug	New	Normal	LKD3588_Debian_U reboot	Debian		Linx	07/15/2024 07:06 PM
452	LP11A	Bug	Closed	Normal	reboot GST 2 reboot /dev/video5	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V1.0\update.img	Linx	07/15/2024 09:10 PM
439	LB120	Bug	New	High	LB120 reboot eth1 reboot 350	Ubuntu	LBA3568_ubuntu20.04_v1.0_20240301_2020.img	Linx	03/29/2024 10:58 AM
434	LP122	Bug	New	Urgent	5G (RM500U-CNV) reboot	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230801_1621.img	Linx	09/25/2024 04:23 PM
429	LP122	Bug	Closed	Urgent	EMMC reboot	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230801_1621.img	Linx	11/15/2024 06:42 PM
427	LP122	Bug	Closed	Urgent	RS232 reboot 115200 reboot 400 reboot reboot	Ubuntu	LZ160_3588_ubuntu20.04_v1.0_20230712_2049	Linx	11/15/2024 06:40 PM
419	LP160	Bug	New	Urgent	3588 reboot 40-50ms reboot 100ms	Ubuntu		Linx	10/16/2023 11:27 AM
382	LP122	Bug	Closed	High	Gstreamer reboot sony1.mp4 dtb id 8	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	Linx	07/28/2023 06:20 PM
377	LP122	Bug	Closed	Normal	/rockchip-test/gpu test_fullscreen_glmak2.sh test_offscreen_glmak2.sh test_stress_glmak2.sh reboot	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	Linx	07/28/2023 04:10 PM
376	LP122	Bug	New	Normal	/rockchip-test/np2 rknn_demo.sh npu_freq_scaling.sh reboot	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	Linx	11/14/2023 04:02 PM

#	Project	Tracker	Status	Priority	Subject	OS	Device	Assignee	Updated
369	LP112	Bug	Closed	Normal	ping command not working	Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230627_1033	Linx	07/17/2023 03:21 PM
366	LP122	Bug	New	Normal	UnixBench & Glmark2-es2 Stream benchmarks	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	Linx	11/14/2023 03:26 PM
364	LP122	Bug	Closed	Normal	timedatectl set-timezone "inactive"	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	Linx	07/20/2023 11:35 AM
363	LP122	Bug	Closed	Normal	5m timeout error	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	Linx	06/30/2023 06:27 PM
362	LP122	Bug	Closed	Normal		Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	Linx	06/30/2023 06:27 PM
360	LP122	Bug	Rejected	Normal	mpv Media Player jellyfish-140-mbps-4k-uhd-hevc-10bit.mkv 8k.mp4	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	Linx	11/15/2024 06:43 PM
358	LP122	Bug	Closed	High	Gstreamer sony1.mp4 gst.sh	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	Linx	07/28/2023 06:20 PM
357	LP122	Bug	Closed	High	emmc /etc/init.d/rockchip.sh	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	Linx	07/28/2023 03:56 PM
356	LP122	Bug	Closed	High	NPU	Ubuntu	LZ120_3568_ubuntu20.04_v1.0_20230616_1402.img	Linx	07/20/2023 11:44 AM
346	LP112	Bug	Closed	Urgent	XML	Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704	Linx	07/03/2023 11:38 AM
345	LP112	Bug	Closed	High	Gstreamer sony1.mp4	Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704	Linx	07/03/2023 01:57 PM
344	LP112	Bug	Closed	High	NPU	Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704	Linx	07/03/2023 10:19 AM
341	LP112	Bug	Closed	High		Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704	Linx	07/18/2023 02:50 PM
340	LP112	Bug	Closed	Normal	gst-play-1.0	Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704	Linx	07/03/2023 01:58 PM
339	LP112	Bug	New	Normal		Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704	Linx	07/18/2023 04:25 PM
338	LP112	Bug	New	High		Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704	Linx	07/14/2023 10:35 AM
336	LP112	Bug	Closed	Urgent	DNS	Ubuntu	lz112_3399pro_ubuntu18.04_v1.0_20230612_1704	Linx	07/03/2023 02:33 PM
333	LP162	Bug	Closed	Normal	Glmark2-es2 Stream RK	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/11/2023 04:13 PM
332	LP162	Bug	Closed	Normal	timedatectl set-timezone "Asia/Shanghai"	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/11/2023 02:33 PM

#	Project	Tracker	Status	Priority	Subject	OS	Image	Assignee	Updated
330	LP162	Bug	New	Normal	Connection Failed Protocol not available.	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/11/2023 03:49 PM
327	LP162	Bug	New	Normal	mpv Media Player "8k.mp4"	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/11/2023 03:57 PM
326	LP162	Bug	New	Normal	mpv Media Player "jellyfish-140-mbps-4k-uhd-hevc-10bit.mkv"	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/11/2023 03:58 PM
323	LP162	Bug	New	Normal	2.0.3.0 ext4	Ubuntu	LZ160_LPB3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/11/2023 03:29 PM
315	LP160	Bug	Closed	Normal	LPA3588_Ubuntu 20.04.5_Glmark2 Stream	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/13/2023 11:53 AM
314	LP160	Bug	Closed	Normal	LPA3588_Ubuntu 20.04.5_RTC timedatectl	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/12/2023 06:18 PM
312	LP160	Bug	Closed	High	LPA3588_Ubuntu 20.04.5_M.2	Ubuntu	LZ160_LPA3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/13/2023 03:27 PM
307	LP112	Feature	Closed	Immediate		Ubuntu	LZ11200001_FT_GB_BASE_230526A.img	Linx	05/30/2023 05:10 PM
306	LP160	Bug	Closed	Normal	LPA3588_Ubuntu 20.04.5_4G_pppd Modem Hangup	Ubuntu	RK3588_UBUNTU_V1_230519.img	Linx	06/09/2023 05:37 PM
304	LP160	Bug	Closed	Normal	LPA3588_Ubuntu 20.04.5_BT	Ubuntu	RK3588_UBUNTU_V1_230519.img	Linx	06/02/2023 04:16 PM
301	LP112	Bug	Closed	Normal	ETH1 MAC	Ubuntu	LZ11200001_FT_GB_BASE_230525A.img	Linx	07/17/2023 03:06 PM
298	LP160	Bug	Closed	Normal	M.2 mount	Ubuntu	LZ160_LKD3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/13/2023 04:44 PM
297	LP160	Bug	Closed	Normal	RTC	Ubuntu	LZ160_LKD3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/13/2023 04:59 PM
295	LP112	Bug	Rejected	Immediate	LP112 lightdm.service glmark2/memtester down hdmi	Ubuntu	update_add_hosts_changelog.img	Linx	05/19/2023 06:06 PM
292	LP160	Bug	Closed	Normal	LPA3588_Ubuntu 20.04.5_USB SD 2.0 3.0 8k *128K *16K *64K	Ubuntu	LZ160_LKD3588_ubuntu20.04_v2.0_20230712_2049.img	Linx	09/13/2023 05:58 PM
286	LP160	Bug	New	Normal	LPA3588_Ubuntu 20.04.5 4k 8k	Ubuntu	LP160XXX03_FT_UBUNTU_F6_V1_230509.img	Linx	06/06/2023 11:39 AM
280	LP112	Bug	New	Normal		Ubuntu	update_add_hosts_changelog.img	Linx	05/17/2023 07:54 PM