

Issues

#	Project	Tracker	Status	Priority	Subject	OS	File Name	Assignee	Updated
793	WIFI	Bug	New	Normal	FD7352S-BS AP		rk3588_debian_wifi_test_7352s_h24.45-B_12_30.img	KuangJie	01/09/2025 01:50 PM
783	WIFI	Bug	New	Urgent	FD7352S-BS STA AX80 udp	Debian	rk3588_debian_wifi_test_7352s_h24.45-B_12_30.img	KuangJie	01/09/2025 01:43 PM
773	WIFI	Bug	New	Normal	FD7352S HE-MCS	Debian	rk3588_debian_wifi_test_7352s_h24.45-B_12_30.img	KuangJie	12/30/2024 06:36 PM
772	LZ210	Bug	New	High	WiFi/BT	Ubuntu	rk3562_lkd210_ubuntu22.04_12_29.img	KuangJie	12/30/2024 10:44 AM
767	LZ210	Bug	New	Normal	reboot log	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	12/26/2024 04:34 PM
765	LZ210	Bug	New	High	CPU GPU NPU	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	01/03/2025 05:48 PM
761	WIFI	Bug	New	Normal	FD7352S-BS	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	KuangJie	12/27/2024 10:28 AM
760	WIFI	Bug	New	Normal	FD7352S-BS	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	KuangJie	12/25/2024 06:05 PM
754	LZ210	Bug	New	High	USB3.0_OTG	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	01/13/2025 09:53 AM
752	WIFI	Bug	New	High	FD7352S-BS AP	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	KuangJie	12/27/2024 10:25 AM
743	LZ210	Bug	New	Urgent	MIPI 3A	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	12/31/2024 02:10 PM
730	LZ210	Bug	New	Normal	Recovery	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	01/03/2025 06:44 PM
726	LZ210	Bug	New	High	system LED	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	01/03/2025 06:54 PM
718	LZ210	Bug	New	Low	4.77 GB 4GB	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	12/31/2024 02:20 PM
712	LP620	Bug	New	Normal	J3200 GPIO	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/13/2024 08:51 PM
707	LP620	Bug	New	Normal	J3300 PWM	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/13/2024 06:02 PM
706	LP620	Bug	New	Normal	LED	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/13/2024 05:57 PM
704	LP620	Bug	New	Normal	WIFI/BT	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/13/2024 04:25 PM
695	LP620	Bug	New	Normal	MIPI TX/MIPI CSI Rx	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/23/2024 10:30 AM
685	LP620	Bug	New	High	Master SSD	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/12/2024 06:53 PM
683	LP620	Bug	New	Normal	TX (ETH1)	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/12/2024 05:45 PM
676	LP620	Bug	New	Urgent		Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/23/2024 09:57 AM
675	LP620	Bug	New	Normal	MIC/HP GPIO	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/12/2024 02:42 PM
673	LP620	Bug	New	High	Onboard EXT SPK	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/12/2024 11:45 AM
669	LP620	Bug	New	High	EHT1	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/23/2024 10:31 AM
667	LP620	Bug	New	High	60s	Ubuntu	Linux_for_Tegra.tar.gz	KuangJie	12/11/2024 06:02 PM
659	WIFI	Bug	New	Normal	AP mcs	Ubuntu	\\192.168.1.250\01-Public\FB101-FD7352\FD7352S-B\update-sdio.img	KuangJie	12/10/2024 05:11 PM
654	WIFI	Bug	New	Normal	wifi	Ubuntu	\\192.168.1.250\01-Public\FB101-FD7352\FD7352S-B\update-sdio.img	KuangJie	12/09/2024 03:33 PM

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
653	WIFI	Bug	New	Normal	FD7352S STA 5G wifi	Ubuntu	\\192.168.1.250\01-Public\FB101-FD7352\FD7352S-B\update-sdio.img	KuangJie	12/09/2024 03:00 PM
634	LP122	Bug	New	High	wifi HE-MCS	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu	KuangJie	11/15/2024 05:26 PM
562	KD16C()	Bug	New	Normal	wifi_ping wlan ping wifi IP	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240806v2.0.img	KuangJie	09/23/2024 11:30 AM
556	WIFI	Bug	New	Urgent	FD7352S, STA 5G/2.4G mcs	Ubuntu	update-sdio.img	KuangJie	09/14/2024 02:28 PM
555	WIFI	Bug	New	Urgent	FD7352S/P AP AP SSID 1 2 SSID	Ubuntu	update-sdio.img	KuangJie	12/18/2024 07:30 PM
553	WIFI	Bug	New	High	FD7352P STA 2.4G ax-40 tx mcs 11 mcs 11 mcs mcs	Ubuntu	update-pcie.img	KuangJie	09/12/2024 01:45 PM
552	WIFI	Bug	New	High	FD7352P STA ac-80 iperf3	Ubuntu	update-pcie.img	KuangJie	09/12/2024 10:31 AM
550	WIFI	Bug	New	High	FD7352P, STA 2.4G n only rx ac.	Ubuntu	update-pcie.img	KuangJie	09/10/2024 04:59 PM
549	WIFI	Bug	New	High	FD7352P, ax80 tx 70. 800~900Mbps/sec 750 Mbps/sec	Ubuntu	update-pcie.img	KuangJie	09/12/2024 01:48 PM
508	KD16C()	Bug	New	Normal		Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240702v1.0.img	KuangJie	08/07/2024 10:40 AM