

Issues

#	Project	Tracker	Status	Priority	Subject			Assignee	Updated
793	WIFI	Bug	New	Normal	FD7352S-BS AP		rk3588_debian_wifi_test_7352s_h24.45-B_12_30.img	KuangJie	01/09/2025 01:50 PM
783	WIFI	Bug	New	Urgent	FD7352S-BS STAAX80 udp	Debian	rk3588_debian_wifi_test_7352s_h24.45-B_12_30.img	KuangJie	01/09/2025 01:43 PM
773	WIFI	Bug	New	Normal	FD7352S HE-MCS	Debian	rk3588_debian_wifi_test_7352s_h24.45-B_12_30.img	KuangJie	12/30/2024 06:36 PM
772	LZ210	Bug	New	High	WiFi/BT	Ubuntu	rk3562_lkd210_ubuntu22.04_12_29.img	KuangJie	12/30/2024 10:44 AM
767	LZ210	Bug	New	Normal	rebootlog	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	12/26/2024 04:34 PM
765	LZ210	Bug	New	High	CPUGPUNPU	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	01/03/2025 05:48 PM
764	WIFI	Bug	Closed	Urgent	FD7352S-BS AP5G N20ping	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	KuangJie	01/08/2025 11:17 AM
762	LZ210	Bug	Closed	High	EMMC	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	01/03/2025 06:09 PM
761	WIFI	Bug	New	Normal	FD7352S-BS	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	KuangJie	12/27/2024 10:28 AM
760	WIFI	Bug	New	Normal	FD7352S-BS	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	KuangJie	12/25/2024 06:05 PM
759	WIFI	Bug	Closed	Normal	FD7352S-BSwifi	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	KuangJie	12/27/2024 05:33 PM
758	WIFI	Bug	Closed	High	FD7352S -BS udp	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	KuangJie	01/08/2025 11:17 AM
757	WIFI	Bug	Closed	Normal	FD7352S -BS STA2.4G N Rx	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	KuangJie	01/09/2025 01:42 PM
756	WIFI	Bug	Closed	Normal	FD7352S-BS STA2.4G WiFi Rx	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	KuangJie	01/09/2025 01:42 PM
755	LZ210	Bug	Closed	Normal	usb2.0	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	01/03/2025 06:10 PM
754	LZ210	Bug	New	High	USB3.0_OTG	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	01/13/2025 09:53 AM
753	WIFI	Bug	Closed	Urgent	wifipingFD7352S-BS	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	KuangJie	01/08/2025 11:18 AM
752	WIFI	Bug	New	High	FD7352S-BSAP	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	KuangJie	12/27/2024 10:25 AM
751	WIFI	Bug	Closed	Urgent	FD7352S-BS AP	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3588\LKD3588\Ubuntu	KuangJie	01/08/2025 11:18 AM
750	LZ210	Bug	Closed	Normal	WIFI/BT	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	01/03/2025 06:15 PM
744	LZ210	Bug	Closed	Low	HDMIHDMI	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	01/03/2025 06:18 PM
743	LZ210	Bug	New	Urgent	MIPI3A	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	12/31/2024 02:10 PM
741	LZ210	Bug	Closed	Normal	SDDiskTool_v1.64u	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	01/03/2025 06:26 PM
735	LZ210	Bug	Closed	Immediate	SIM4G	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	01/03/2025 06:43 PM
730	LZ210	Bug	New	Normal	Recovery	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	KuangJie	01/03/2025 06:44 PM

#	Project	Tracker	Status	Priority	Subject	OS	File Path	Assignee	Updated
726	LZ210	Bug	New	High	system LED 不亮	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Kuangjie	01/03/2025 06:54 PM
718	LZ210	Bug	New	Low	内存4.77 GB 4GB	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Kuangjie	12/31/2024 02:20 PM
712	LP620	Bug	New	Normal	J3200 GPIO 不工作	Ubuntu	Linux_for_Tegra.tar.gz	Kuangjie	12/13/2024 08:51 PM
708	LP620	Bug	Closed	High	GPIO 485/460 不工作	Ubuntu	Linux_for_Tegra.tar.gz	Kuangjie	01/03/2025 09:07 PM
707	LP620	Bug	New	Normal	J3300 PWM 不工作	Ubuntu	Linux_for_Tegra.tar.gz	Kuangjie	12/13/2024 06:02 PM
706	LP620	Bug	New	Normal	LED 不亮	Ubuntu	Linux_for_Tegra.tar.gz	Kuangjie	12/13/2024 05:57 PM
704	LP620	Bug	New	Normal	WiFi/BT 不工作	Ubuntu	Linux_for_Tegra.tar.gz	Kuangjie	12/13/2024 04:25 PM
701	WiFi 不工作	Bug	Closed	Low	wifi 连接不上 AP 点	Ubuntu	\\192.168.1.250\01-Public\测试\FB101-FD7352\测试\FD7352S-B\update-sdio.img	Kuangjie	01/08/2025 11:18 AM
695	LP620	Bug	New	Normal	MIPI TX/MIPI CSI Rx 不工作	Ubuntu	Linux_for_Tegra.tar.gz	Kuangjie	12/23/2024 10:30 AM
685	LP620	Bug	New	High	Master SSD 不工作	Ubuntu	Linux_for_Tegra.tar.gz	Kuangjie	12/12/2024 06:53 PM
683	LP620	Bug	New	Normal	串口 TX 不工作 (ETH1)	Ubuntu	Linux_for_Tegra.tar.gz	Kuangjie	12/12/2024 05:45 PM
676	LP620	Bug	New	Urgent	摄像头 不工作	Ubuntu	Linux_for_Tegra.tar.gz	Kuangjie	12/23/2024 09:57 AM
675	LP620	Bug	New	Normal	MIC/HP 不工作 GPIO 不工作	Ubuntu	Linux_for_Tegra.tar.gz	Kuangjie	12/12/2024 02:42 PM
673	LP620	Bug	New	High	Onboard EXT SPK 不工作	Ubuntu	Linux_for_Tegra.tar.gz	Kuangjie	12/12/2024 11:45 AM
669	LP620	Bug	New	High	摄像头 EHT1 不工作	Ubuntu	Linux_for_Tegra.tar.gz	Kuangjie	12/23/2024 10:31 AM
667	LP620	Bug	New	High	摄像头 60s 不工作	Ubuntu	Linux_for_Tegra.tar.gz	Kuangjie	12/11/2024 06:02 PM
661	WiFi 不工作	Bug	Closed	Urgent	5GHz AP 不工作 5GHz AP	Ubuntu	\\192.168.1.250\01-Public\测试\FB101-FD7352\测试\FD7352S-B\update-sdio.img	Kuangjie	12/23/2024 10:02 AM
660	WiFi 不工作	Bug	Closed	Normal	5G AP 不工作	Ubuntu	\\192.168.1.250\01-Public\测试\FB101-FD7352\测试\FD7352S-B\update-sdio.img	Kuangjie	01/08/2025 11:19 AM
659	WiFi 不工作	Bug	New	Normal	AP mcs 不工作	Ubuntu	\\192.168.1.250\01-Public\测试\FB101-FD7352\测试\FD7352S-B\update-sdio.img	Kuangjie	12/10/2024 05:11 PM
655	WiFi 不工作	Bug	Closed	Urgent	FD7352S, STA 2.4G 不工作	Ubuntu	\\192.168.1.250\01-Public\测试\FB101-FD7352\测试\FD7352S-B\update-sdio.img	Kuangjie	12/23/2024 10:02 AM
654	WiFi 不工作	Bug	New	Normal	wifi 不工作	Ubuntu	\\192.168.1.250\01-Public\测试\FB101-FD7352\测试\FD7352S-B\update-sdio.img	Kuangjie	12/09/2024 03:33 PM
653	WiFi 不工作	Bug	New	Normal	FD7352S, STA 5G 不工作 wifi 不工作	Ubuntu	\\192.168.1.250\01-Public\测试\FB101-FD7352\测试\FD7352S-B\update-sdio.img	Kuangjie	12/09/2024 03:00 PM
634	LP122	Bug	New	High	wifi HE-MCS 不工作	Ubuntu	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu	Kuangjie	11/15/2024 05:26 PM
562	KD16C (测试)	Bug	New	Normal	wifi ping wln0 ping wifi IP	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240806v2.0.img	Kuangjie	09/23/2024 11:30 AM
556	WiFi 不工作	Bug	New	Urgent	FD7352S, STA 5G/2.4G 不工作 mcs 不工作	Ubuntu	update-sdio.img	Kuangjie	09/14/2024 02:28 PM

#	Project	Tracker	Status	Priority	Subject	OS	File Name	Assignee	Updated
555	WIFI	Bug	New	Urgent	FD7352S/P AP 2 SSID 1 2 SSID	Ubuntu	update-sdio.img	KuangJie	12/18/2024 07:30 PM
554	WIFI	Bug	Closed	Urgent	FD7352S, wifi apt update, 2	Ubuntu	update-sdio.img	KuangJie	09/14/2024 09:56 AM
553	WIFI	Bug	New	High	FD7352P STA 2.4G ax-40 tx mcs 11 mcs 1 mcs mcs	Ubuntu	update-pcie.img	KuangJie	09/12/2024 01:45 PM
552	WIFI	Bug	New	High	FD7352P STA ac-80 iperf3	Ubuntu	update-pcie.img	KuangJie	09/12/2024 10:31 AM
550	WIFI	Bug	New	High	FD7352P, STA 2.4G n only rx ac. n ac	Ubuntu	update-pcie.img	KuangJie	09/10/2024 04:59 PM
549	WIFI	Bug	New	High	FD7352P, ax80 tx 70. 800~900Mbps/sec 750 Mbps/sec	Ubuntu	update-pcie.img	KuangJie	09/12/2024 01:48 PM
510	KD16C()	Bug	Closed	Normal	Neardi	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240806v2.0.img	KuangJie	12/31/2024 02:25 PM
508	KD16C()	Bug	New	Normal		Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240702v1.0.img	KuangJie	08/07/2024 10:40 AM
502	KD16C()	Bug	Closed	Normal	wifi wpa_supplicant.conf WIFI	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240702v1.0.img	KuangJie	12/31/2024 02:22 PM
474	KD16C()	Bug	Closed	Normal	GPS, minicom cat \$GNTXT NMEA unknown	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240702v1.0.img	KuangJie	07/08/2024 01:39 PM