

Issues

#	Project	Tracker	Status	Priority	Subject	OS	Image	Assignee	Updated
860	LP201	Bug	New	High	CR	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	03/04/2025 03:09 PM
857	LP201	Bug	New	High	RTC	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	03/03/2025 04:04 PM
819	LP201	Bug	New	Normal	2280M.2	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/23/2025 09:52 AM
818	LP201	Bug	New	High	HDMI	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/22/2025 12:00 PM
817	LP201	Bug	New	High	SIM	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/22/2025 10:56 AM
813	LP201	Bug	New	High	D/I GPIO55	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/21/2025 03:56 PM
812	LP201	Bug	New	High	D/O	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/21/2025 10:54 AM
811	LP201	Bug	New	Normal	reboot--SPK	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/22/2025 11:01 AM
809	LP201	Bug	New	High	Type-C	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/16/2025 05:56 PM
749	LB700	Bug	New	High		Ubuntu		shiliang	12/23/2024 04:05 PM
747	LB700	Bug	New	High		Ubuntu		shiliang	12/23/2024 02:34 PM
746	LB700	Bug	New	Normal		Ubuntu		shiliang	12/23/2024 02:27 PM
745	LB700	Bug	New	High		Ubuntu		shiliang	12/23/2024 02:24 PM
700	LB700	Bug	New	Normal	J2500	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	shiliang	03/06/2025 03:20 PM
689	LB700	Bug	New	Normal	Mini-PCIE	Ubuntu	https://forum.neardi.com/d/126-hisi3403-xia-zai-gu-jian	shiliang	12/13/2024 10:41 AM
476	KD16C	Bug	New	High	USB1_3.0U	Ubuntu	rk3588-kd16c-ubuntu20.04-TongLuYun-20240702v1.0.img	shiliang	07/08/2024 06:18 PM
438	PX30	Bug	New	Normal	LCM		-	shiliang	03/18/2024 05:02 PM
300	KZ117	Bug	New	Normal		Ubuntu	KZ11A664_RL_LB_BASE_V01_20230505.img	shiliang	05/22/2023 08:44 PM