

Issues

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
1058	LZ230	Bug	New	High	LZ230_LED	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3506\BGA_EMMC\25_07_01_buildroot		07/08/2025 10:21 AM
1042	Ubuntu_2.04	Bug	New	Normal	LPB3568 HDMI_OUT1(hdmi) hdmi	Ubuntu	LPB3568_ubuntu22.04_v1.0_20250421_1349.img		07/04/2025 10:17 AM
1041	Ubuntu_2.04	Bug	New	High	LPB3568 HDMI_OUT1(hdmi) hdmi hdmi	Ubuntu	LPB3568_ubuntu22.04_v1.0_20250421_1349.img	Linx	07/04/2025 09:37 AM
1038	Ubuntu_2.04	Bug	New	Normal	LPB3568 log RK neardi_log	Ubuntu	LPB3568_ubuntu22.04_v1.0_20250421_1349.img	Linx	07/03/2025 06:48 PM
1036	Ubuntu_2.04	Bug	New	High	LPB3568 HDMI_OUT2 mipi edid 1920*1080	Ubuntu	LPB3568_ubuntu22.04_v1.0_20250421_1349.img		07/03/2025 06:48 PM
1033	Ubuntu_2.04	Bug	New	High	LPB3568 TF img HDMI_OUT1	Ubuntu	LPB3568_ubuntu22.04_v1.0_20250421_1349.img	Linx	07/03/2025 04:34 PM
1032	Ubuntu_2.04	Bug	New	Normal	LPB3568 U	Ubuntu	LPB3568_ubuntu22.04_v1.0_20250421_1349.img	Linx	07/03/2025 04:10 PM
1028	Ubuntu_2.04	Bug	New	Normal	LPB3568 WAN_LAN_MAC	Ubuntu	LPB3568_ubuntu22.04_v1.0_20250421_1349.img	Linx	07/03/2025 03:38 PM
1022	Ubuntu_2.04	Bug	New	Normal	LPB3568	Ubuntu	LPB3568_ubuntu22.04_v1.0_20250421_1349.img	Linx	07/03/2025 02:17 PM
1008	Ubuntu_2.04	Bug	New	High	LKD3568 rk3568 V 6.1.99 RTC	Ubuntu	LKD3568_ubuntu22.04_v1.0_20250409_1527.img		07/04/2025 10:19 AM
1000	LZ230	Bug	New	Urgent	LZ230	Ubuntu	rk3506b_neardi_lz230_buildroot_25_05_15.img		06/24/2025 10:06 AM
991	LZ201	Bug	New	Urgent	-25°~-40° 20%	Ubuntu	rk3576_ubuntu2204_20250522.img		06/20/2025 02:49 PM
953	LZ201	Bug	New	Urgent	3 mipi	Ubuntu	rk3576_ubuntu2204_20250429.img		06/12/2025 03:28 PM
947	LZ210	Bug	New	High	RK3562J	Ubuntu	rk3562_ubuntu2204_20250409A.img	zenghui	05/14/2025 10:24 AM
943	LZ210	Bug	New	High	RK3562J 70° DCDC	Ubuntu	rk3562_ubuntu2204_20250409A.img	zenghui	05/12/2025 06:43 PM
923	LZ210	Bug	New	Urgent	RK3562J sudo -i cpu	Ubuntu	rk3562_ubuntu2204_20250409A.img	Linx	05/09/2025 01:49 PM
907	LZ210	Bug	New	Urgent	usb3.0hub U	Ubuntu	\\192.168.1.250\01-Public\Linux\rk3562\20250321	Linx	04/01/2025 09:46 AM
885	KP12C	Bug	New	Urgent	FD7352Swift	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\kp12c\KP12C_4_1080_Ubuntu20.04_v1.0_20250117		03/17/2025 09:40 AM
884	LZ201	Bug	New	Urgent	can can can	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\Linux\2025_03_10		03/11/2025 04:22 PM
857	LP201	Bug	New	High	RTC	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	03/03/2025 04:04 PM
855	LZ750	Bug	New	High		Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	sun	02/28/2025 02:14 PM

#	Project	Tracker	Status	Priority	Subject	OS	Path	Assignee	Updated
854	LZ750	Bug	New	Normal	XXXXXXXXXXXX	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	Linx	02/28/2025 02:23 PM
851	LP201	Bug	New	High	XXXXXXXXXXXXcat /dev/ttyS3XXXXXXXXXXXXBDGGA XXXXXXXXXXXXBDGSV	Ubuntu	ubuntu22.04_lb201_25_01_07.img	jj	02/27/2025 06:53 PM
850	LZ750	Bug	New	High	MICXXXXXXXXXXXXMICXXXXXXXXXXXX	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	jing	02/28/2025 02:18 PM
849	LZ750	Bug	New	High	XXXXMINI PCIEXXXXM.2	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	jing	02/27/2025 05:15 PM
848	LZ750	Bug	New	Urgent	XXXXPCIE/XXXX	Ubuntu	ubuntu22.04_V1.3_2G_DDR_OS_1.5G-20250606	jing	06/18/2025 11:47 AM
847	LZ750	Bug	New	High	XXXXXXXXXXXX5GXXXXXXXXXXXX	Ubuntu	\\192.168.1.250\03-image\hisi3402\imageOS\ubuntu\ubuntu_V1.0-20250225	sun	02/28/2025 02:17 PM
844	LB700	Bug	New	High	audiodemoaudio	Ubuntu	\\192.168.1.250\03-image\hisi3403\imageOS\ubuntu\ss928\ubuntu_V1.3-support-UI-20250304	Linx	04/18/2025 06:38 PM
834	LZ201	Bug	New	Normal	XXHDMIHDMI SPK	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/14/2025 02:42 PM
833	LZ201	Bug	New	Normal	4gethXXXXXXXXXXXX4gDNS	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	Linx	02/13/2025 05:58 PM
832	LZ201	Bug	New	Normal	SPKXXXXXXXXXXXX	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/13/2025 01:51 PM
831	LZ201	Bug	New	Normal	XXXXXXXXXXXXpop/reboot	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/13/2025 01:46 PM
829	LZ201	Bug	New	Normal	HDMItype-cDPHDMI	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	Linx	05/23/2025 02:27 PM
828	LZ201	Bug	New	Low	XXXX 4.78GB4GB	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	Linx	02/10/2025 04:08 PM
827	LZ201	Bug	New	High	TPXXXXXXXXXXXX	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/08/2025 06:15 PM
826	LZ201	Bug	New	High	MIPI DSI TX mipiXXXXXXXXXXXX	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/08/2025 06:13 PM
825	LZ201	Bug	New	High	XXWORKXXXXXXXXXXXX	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	jing	02/08/2025 11:34 AM
822	LZ201	Bug	New	Normal	XXXXrootXXXXXXXXXXXXgst-launch-1.0XXXXXXXXXXXX	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	Linx	02/06/2025 02:00 PM
821	LZ201	Bug	New	Urgent	MIPIXXXXXXXXXXXX3A	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3576\lz201\2025-01-23	Linx	02/06/2025 01:40 PM
819	LP201	Bug	New	Normal	XXXX2280M.2	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/23/2025 09:52 AM
818	LP201	Bug	New	High	HDMI FPC	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/22/2025 12:00 PM
817	LP201	Bug	New	High	XXSIMXXXXSIMXXXXXXXXXXXX	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/22/2025 10:56 AM
816	LP201	Bug	New	High	rootfsXXXXXXXXXXXXNetworkManager-wait-online.service 27.848s	Ubuntu	ubuntu22.04_lb201_25_01_07.img	Linx	01/22/2025 11:46 AM
814	LP201	Bug	New	Normal	ubuntudebian 1080P301080P60XXXXXXXXXXXXbuildroot	Ubuntu	ubuntu22.04_lb201_25_01_07.img	Linx	01/21/2025 04:23 PM
813	LP201	Bug	New	High	XXXXXXXXXXXXD/I GPIO55XXXXXXXXXXXX	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/21/2025 03:56 PM
812	LP201	Bug	New	High	D/OXXXX12VXXXXXXXXXXXX	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/21/2025 10:54 AM
811	LP201	Bug	New	Normal	XXXXreboot--SPKpop	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/22/2025 11:01 AM

#	Project	Tracker	Status	Priority	Subject	OS	File Path	Assignee	Updated
809	LP201	Bug	New	High	Type-C 000000000000	Ubuntu	ubuntu22.04_lb201_25_01_07.img	shiliang	01/16/2025 05:56 PM
808	KP12C	Bug	New	High	000LP120_4_1080_Ubuntu20.04_v1.0_20250110.img TF000000	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img	00	01/15/2025 05:55 PM
796	KP12C	Bug	New	Normal	usb2.0 0usb3.0 hub 30%000000	Ubuntu	\\192.168.1.250\01-Public\wilson_test\rk3568\lpa3568\4x1080\LP120_4_1080_Ubuntu20.04_v1.0_20250110\LP120_4_1080_Ubuntu20.04_v1.0_20250110.img	Linx	01/14/2025 11:54 AM
792	LP201	Bug	New	High	LCD00000000	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/09/2025 10:04 AM
790	LP201	Bug	New	High	0000000000000000	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/08/2025 08:02 PM
789	LP201	Bug	New	High	RS485/CAN00000000	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/08/2025 07:57 PM
787	LP201	Bug	New	Urgent	00000000000003-5000000000	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/22/2025 10:42 AM
786	LZ130	Bug	New	High	00000000	Ubuntu		jing	01/08/2025 05:48 PM
785	LP201	Bug	New	Immediate	00000000000000	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/08/2025 06:19 PM
782	LP201	Bug	New	High	00eth100000000	Ubuntu	ubuntu22.04_lb201_25_01_07.img		02/26/2025 03:49 PM
781	LP201	Bug	New	High	DC/IN0000000000	Ubuntu	ubuntu22.04_lb201_25_01_07.img		01/08/2025 11:32 AM
780	LZ210	Bug	New	Low	C2045 0J92000000000000000000000000000000	Ubuntu	rk3562_lkd210_ubuntu22.04_12_29.img	zenghui	01/08/2025 10:47 AM
776	LP112	Bug	New	High	USB2.0000000000USB1.00000000	Ubuntu	LZ112_3588_ubuntu20.04_v1.0_20240204_1649	00	01/02/2025 02:05 PM
771	LZ210	Bug	New	High	000000000000000000	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/27/2024 09:06 PM
770	LZ210	Bug	New	Normal	ADC_IN000000voltage_raw000000000	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/27/2024 05:44 PM
769	LZ210	Bug	New	Urgent	ADC_IN0000000000000.1V00000000	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/27/2024 05:46 PM
763	LZ210	Bug	New	Normal	4k00000000	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	12/25/2024 08:18 PM
748	LZ210	Bug	New	High	root0000000000gst-00000000000000	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	01/10/2025 10:15 AM
743	LZ210	Bug	New	High	MIPI00000000003A00	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	05/09/2025 01:57 PM
742	LZ210	Bug	New	High	000000000000POP0	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	12/24/2024 04:53 PM
738	LZ210	Bug	New	High	LC2100000000000000000000000000000000SOC00	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	000	12/20/2024 04:24 PM
733	LZ210	Bug	New	Normal	00000000000000000000000000000000	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	Linx	05/12/2025 06:45 PM
728	LZ210	Bug	New	High	power 000000000000	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	zenghui	05/13/2025 11:50 AM
718	LZ210	Bug	New	Low	00004.77 GB04GB	Ubuntu	rk3562_lkd210_ubuntu22.04_12_13.img	k	05/13/2025 11:41 AM
671	LZ210	Bug	New	Immediate	emmc00000	Ubuntu	rk3562_lkd210_ubuntu2004.img	00	01/03/2025 06:57 PM