

Ubuntu_22.04 - Bug #1033

LPB3568 TF img HDMI_OUT1_

07/03/2025 04:34 PM -

Status:	New	Start date:	07/03/2025
Priority:	High	Due date:	
Assignee:	Linx	% Done:	0%
Category:	S.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LP120	:	Linux RK356X 6.1.99 #2 SMP Tue Apr 8 17:43:27 CST 2025 aarch64 aarch64 aarch64 GNU/Linux
CPU:	RK3568	APP :	-
:	LPB3568	:	100%
/ :	05	:	FD7352S
:	04	:	YT8521SC
/ :	04	EMMC :	-
:	LPB3568_ubuntu22.04_v1.0_20250421_1349.img	:	Burn In && Update
:	Ubuntu		
Description			