

Ubuntu_22.04 - Bug #1040

LPA3588_Ubuntu22.04 HDMI_Out2_

07/03/2025 06:44 PM - mike

Status: Priority: Assignee: Category: Target version: CPU:	New Normal sun Driver LP160 RK3588 LPA3588 05 01 02 LPA3588_ubuntu22.04_v1.0_20250415_1601.img Ubuntu	Start date: Due date: % Done: Estimated time: Spent time: APP EMMC	07/03/2025 0% 0.00 hour 0.00 hour Linux LPA3588 6.1.84 #1 SMP Wed Apr 9 11:21:26 CST 2025 aarch64 aarch64 aarch64 GNU/Linux - 100% FD7352S YT8521SC - HDMI_LVDS_eDP
Description HDMI_Out 1 & 2 Prot HDMI Out 1 -- HDMI Out 2 --			