

LZ730(Hi3519 DV500) - Bug #1051

J3504 camera

07/04/2025 05:00 PM -

|                               |        |                        |                       |
|-------------------------------|--------|------------------------|-----------------------|
| <b>Status:</b>                | New    | <b>Start date:</b>     | 07/04/2025            |
| <b>Priority:</b>              | High   | <b>Due date:</b>       |                       |
| <b>Assignee:</b>              | sun    | <b>% Done:</b>         | 0%                    |
| <b>Category:</b>              | Driver | <b>Estimated time:</b> | 0.00 hour             |
| <b>Target version:</b>        |        | <b>Spent time:</b>     | 0.00 hour             |
| <b> :</b>                     |        | <b> :</b>              | busybox_V1.0-20250627 |
| <b>CPU:</b>                   |        | <b> :</b>              |                       |
| <b> :</b>                     |        | <b> :</b>              | Linux (none) 5.10.0   |
| <b> / :</b>                   |        | <b> :</b>              |                       |
| <b> :</b>                     |        | <b> :</b>              |                       |
| <b> / :</b>                   | 01     | <b>EMMC :</b>          | -                     |
| <b>Description</b>            |        |                        |                       |
| J3504demoos04a10J3505mini lcd |        |                        |                       |