


Ubuntu_22.04 - Bug #1103

LPA3588_Ubuntu22.04 8

07/28/2025 02:35 PM - mike

Status:	New	Start date:	07/28/2025
Priority:	Normal	Due date:	
Assignee:	jing	% Done:	0%
Category:	H.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
 :	LP160	 :	Linux LPA3588 6.1.84 #79 SMP Thu Apr 17 18:28:02 CST 2025 aarch64 aarch64 aarch64 GNU/Linux
CPU:	RK3588	APP :	-
 :	LPA3588	 :	100%
 / :	06	 :	FD7352S
 :	01	 :	YT8521SC
 / :	03	EMMC :	-
 :	LPA3588_ubuntu22.04_v1.0_20250415_1601.img	 :	Camera
 :	Ubuntu	4G/5G/GPS:	RM500U 5G 4*5G M.2
Description			
中心 55.0℃ 最高 55.8 最低 29.2  55.8 9922			

Files			
clipboard-202507281432-cb3cq.png	153 KB	07/28/2025	mike