

LB220 - Bug #1132

5G

08/15/2025 10:02 AM -

Status:	New	Start date:	08/15/2025
Priority:	High	Due date:	
Assignee:		% Done:	0%
Category:	H.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LB220	:	\\192.168.1.250\01-Public\wilson_test\rk3528\25_07_23_debian
CPU:	RK3528A	:	Debian
:		:	
/ :		:	
:		:	
/ :	01	EMMC :	-
Description ID isusb fail root@linaro-alip:/home/linaro/demos# /usr/local/bin/quectel-CM &[1] 3636root@linaro-alip:/home/linaro/demos# [08-14_07:36:30:934] QConnectManager_Linux_V1.6.5[08-14_07:36:30:937] Find /sys/bus/usb/devices/1-1.4 idVendor=0x2c7c idProduct=0x900, bus=0x001, dev=0x004[08-14_07:36:30:938] network interface " or qmidev " is not exist[08-14_07:36:30:939] atdevice_detect failed[08-14_07:36:30:939] qmidevice_detect failed [1]+ /usr/local/bin/quectel-CMroot@linaro-alip:/home/linaro/demos# RG200U RG200U			

History

- #1 - 08/15/2025 04:48 PM -
- 5Gusb3.0usb3.0
- #2 - 08/15/2025 06:18 PM -
- Subject changed from 5G RM500U to 5G
- Description updated
- Category changed from Driver to H.W
- Assignee changed from to