

# KD17A - Bug #437

eth LPM3588 iperf3

03/13/2024 11:20 AM

<b>Status:</b>	Closed	<b>Start date:</b>	03/13/2024
<b>Priority:</b>	High	<b>Due date:</b>	
<b>Assignee:</b>	sun	<b>% Done:</b>	0%
<b>Category:</b>	Driver	<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>		<b>Spent time:</b>	0.00 hour
<b>OS:</b>	KZ17A	<b>OS:</b>	Ubuntu
<b>CPU:</b>	RK3588S	<b>RAM:</b>	20.04
<b>OS:</b>	KZ17A	<b>APP:</b>	
<b>OS/Kernel:</b>	01	<b>OS/Kernel:</b>	
<b>OS/Kernel:</b>	01	<b>OS/Kernel:</b>	
<b>OS/Kernel:</b>		<b>OS/Kernel:</b>	
<b>OS/Kernel:</b>	update.img	<b>EMMC:</b>	

## Description

1 ethtool eth0  
2 ethtool -s eth0 speed 1000  
3 LPM3588  
4 iperf3  
iperf3

## History

#1 - 03/18/2024 04:31 PM

- File 57858dcb0103f3ea2eaf634a0380c14.png added
- File 4d27803288522f7ea95230c292feedc.png added

#2 - 03/20/2024 09:53 AM

- Status changed from New to Closed

iperf3

## Files

57858dcb0103f3ea2eaf634a0380c14.png	24.5 KB	03/18/2024	
4d27803288522f7ea95230c292feedc.png	2.37 KB	03/18/2024	