

LP11A - Bug #462

3PIN LCD

06/12/2024 10:01 AM - mike

Status:	Closed	Start date:	06/12/2024
Priority:	Urgent	Due date:	
Assignee:	jing	% Done:	0%
Category:	H.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LP11A	:	
CPU:	RK3399Pro	:	Linux bionic 4.4.194 #1 SMP Sat May 18 10:51:08 CST 2024 aarch64 aarch64 aarch64 GNU/Linux
:		APP:	-
/ :	-	:	
:	03	:	
/ :	02	:	
:	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V1.0\update.img	EMMC:	

Description



History

- #1 - 06/13/2024 03:01 PM -
pcb
- #2 - 06/13/2024 03:02 PM - mike
- Category changed from Driver_[RK3568/RK3399Pro] to H.W
- Assignee changed from to jing
- #3 - 06/13/2024 03:09 PM - jing
AHD ESD E1901 BV03C ESD 30V 180
- #4 - 07/09/2024 01:46 PM - shiliang
- Status changed from New to Closed

Files

clipboard-202406120959-6tdkz.png	143 KB	06/12/2024	mike
----------------------------------	--------	------------	------