


LP11A - Bug #468

Cam 1~4 90°

06/19/2024 09:15 PM - mike

Status:	Closed	Start date:	06/19/2024
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:	Driver_[RK3568/RK3399Pro]	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LP11A	:	Ubuntu
CPU:	RK3399Pro	:	Linux version 4.4.194 (yangyonghao@ubuntu2004) (gcc version 6.3.1 20170404 (Linaro GCC 6.3-2017.05)) #11 SMP Tue Jun 18 18:51:06 CST 2024
:		APP:	-
/:	-	:	
:	03	:	
/:	02	:	
:	\\192.168.1.250\01-Public\wilson_test\rk 3399pro\linux\aidong\update.img	EMMC:	

Description



1. 90°

History

#1 - 07/12/2024 11:30 AM -

ahd

#2 - 07/12/2024 11:30 AM -

- Status changed from New to Closed

Files

clipboard-202406192037-ondpv.png	60.5 KB	06/19/2024	mike
clipboard-202406192037-pm6oa.png	293 KB	06/19/2024	mike