

KD17A - Bug #492

KD17A, iperf3 100Mbps/sec . 500-600Mbps/sec

07/17/2024 02:16 PM -

Status:	New	Start date:	07/17/2024
Priority:	High	Due date:	
Assignee:	sun	% Done:	0%
Category:	H.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
OS:	KZ17A	OS:	Ubuntu
CPU:	RK3588S	Kernel:	20.04
Model:	KZ17A	APP:	
Board/Device:	04	Board:	
Partition:	01	Partition:	
Board/Device:	04	Partition:	
Kernel:	KZ17A_ubuntu20.04_v1.9_fixed_fd7352s_crash_20240708.img	EMMC:	

Description

1 iperf3, STA
2 WiFi
3 iperf3
AP6275s FD7352s 100Mbps/sec

```
[SUM] 9.03-10.00 sec 10.8 MBytes 92.7 Mbits/sec 455
[ ID] Interval Transfer Bitrate Retr
[ 5] 0.00-10.02 sec 19.2 MBytes 16.1 Mbits/sec 700 sender
[ 8] 0.00-10.02 sec 21.2 MBytes 17.7 Mbits/sec 763 sender
[10] 0.00-10.02 sec 21.7 MBytes 18.2 Mbits/sec 831 sender
[12] 0.00-10.02 sec 18.6 MBytes 15.6 Mbits/sec 643 sender
[14] 0.00-10.02 sec 17.8 MBytes 14.9 Mbits/sec 720 sender
[16] 0.00-10.02 sec 15.2 MBytes 12.7 Mbits/sec 541 sender
[SUM] 0.00-10.02 sec 114 MBytes 95.2 Mbits/sec 4198 sender

Server listening on 5201
Accepted connection from 192.168.10.3, port 64498
[ 5] local 192.168.10.4 port 5201 connected to 192.168.10.3 port 64500
[ 8] local 192.168.10.4 port 5201 connected to 192.168.10.3 port 64501
[10] local 192.168.10.4 port 5201 connected to 192.168.10.3 port 64502
[12] local 192.168.10.4 port 5201 connected to 192.168.10.3 port 64503
[14] local 192.168.10.4 port 5201 connected to 192.168.10.3 port 64504
[16] local 192.168.10.4 port 5201 connected to 192.168.10.3 port 64505
[ ID] Interval Transfer Bitrate
[ 5] 0.00-1.00 sec 1.74 MBytes 14.6 Mbits/sec
[ 8] 0.00-1.00 sec 1.91 MBytes 16.0 Mbits/sec
[10] 0.00-1.00 sec 1.98 MBytes 16.6 Mbits/sec
[12] 0.00-1.00 sec 1.75 MBytes 14.7 Mbits/sec
```

Files

clipboard-202407171415-c8qcc.png	42.4 KB	07/17/2024	
----------------------------------	---------	------------	--