

LP11A - Feature #506

USB MaskRom

07/26/2024 09:55 PM - mike

Status:	Closed	Start date:	07/26/2024
Priority:	Normal	Due date:	
Assignee:	jing	% Done:	0%
Category:	H.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
OS:	LP11A	OS:	Ubuntu
CPU:	RK3399Pro	Kernel:	Linux version 4.4.194 (yangyonghao@ubuntu2004) (gcc version 6.3.1 20170404 (Linaro GCC 6.3-2017.05)) #76 SMP Wed Jul 17 15:08:42 CST 2024
APP:		APP:	-
Progress:	-	Progress:	100%
Build:	03	Build:	
Path:	03	Path:	
Location:	\\192.168.1.250\01-Public\wilson_test\rk3399pro\linux\aidong\V3.0\update.img	EMMC:	


Description

"loader"

发现一个LOADER设备

```
CLK: (uboot. a
CLK: (uboot. a
aplll 816000
apllb 816000
dpll 856000
cp1l 24000 K
gp1l 800000
np1l 600000
vp1l 24000 KHz
aclk_perihp 133333 KHz
hclk_perihp 66666 KHz
pclk_perihp 33333 KHz
aclk_perilp0 266666 KHz
hclk_perilp0 88888 KHz
pclk_perilp0 44444 KHz
hclk_perilp1 100000 KHz
pclk_perilp1 50000 KHz
EC20_PWREN = 1
EC20_RESET = 0
----- ec20_init -----
EC20_PWRKEY = 0
EC20_PWRKEY = 1
Net: No ethernet found.
RKUSB: LUN 0, dev 0, hwpart 0, sector 0x0, count 0x1d1f000
\
```

USB "MaskRom"



History

#1 - 08/14/2024 10:19 AM - shiliang

featureclose

#2 - 08/14/2024 10:50 AM - mike

- Tracker changed from Bug to Feature
- Status changed from New to Closed

Files

clipboard-202407262153-5ohew.png	22.3 KB	07/26/2024	mike
clipboard-202407262154-3v5i9.png	23.4 KB	07/26/2024	mike