

LP11A - Bug #529

eth0 Mac eth1 Mac

08/28/2024 05:16 PM - EGON

Status:	Closed	Start date:	08/28/2024
Priority:	High	Due date:	
Assignee:		% Done:	0%
Category:	Driver_[RK3568/RK3399Pro]	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LB120	:	Ubuntu
CPU:	RK3568	:	Linux version 5.10.198 (yangyonghao@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #11 SMP Wed Aug 14 17:46:10 CST 2024
:	LPA3568M8"	APP:	
/:	04	:	100%
:	04	:	
/:	05	:	
:	\\192.168.1.250\01-Public\wilson_test\rk 3568\lpa3568	EMMC:	

Description

eth0 Mac eth1 Mac

```
eth0: flags=4163<UP,BROADCAST,RUNNING,MULTICAST> mtu 1500
    inet 192.168.1.100 netmask 255.255.255.0 broadcast 192.168.1.255
    ether 46:87:84:62:e2:19 txqueuelen 1000 (Ethernet)
    RX packets 334202 bytes 22086266 (22.0 MB)
    RX errors 0 dropped 0 overruns 0 frame 0
    TX packets 104366 bytes 5994874212 (5.9 GB)
    TX errors 0 dropped 0 overruns 0 carrier 0 collisions 0
    device interrupt 48

eth1: flags=4099<UP,BROADCAST,MULTICAST> mtu 1500
    ether 42:87:84:62:e2:19 txqueuelen 1000 (Ethernet)
    RX packets 1927 bytes 173245 (173.2 KB)
    RX errors 0 dropped 0 overruns 0 frame 0
    TX packets 40 bytes 6515 (6.5 KB)
    TX errors 0 dropped 0 overruns 0 carrier 0 collisions 0
    device interrupt 58
```

History

#1 - 09/27/2024 10:08 AM - mike

#2 - 09/27/2024 10:09 AM - mike

- Status changed from New to Closed

Files

000000_17248291557283.png	30.3 KB	08/28/2024	EGON
---------------------------	---------	------------	------