

LP120 - Bug #544

□ □ □ □ □ □ □ □

09/04/2024 10:56 AM - EGON

Status:	Closed	Start date:	09/04/2024
Priority:	High	Due date:	
Assignee:	□ □	% Done:	0%
Category:	S.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
□ □ :	LB120	□ □ :	Ubuntu
CPU:	RK3568	□ □ □ □ :	Linux version 5.10.198 (yangyonghao@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #11 SMP Wed Aug 14 17:46:10 CST 2024
□ □ :	LPA3568M8□ □ □ □ "	APP□ □ :	
□ □ /□ □ □ □ □ □ □ □ :	04	□ □ □ □ :	100%
□ □ □ □ □ □ □ □ :	04	□ □ □ □ :	
□ □ /□ □ □ □ □ □ □ □ :	05	□ □ □ □ □ :	
□ □ □ □ :	\\192.168.1.250\01-Public\wilson_test\rk 3568\lpa3568	EMMC□ □ :	

Description

1.□ □ □ □ □ □ □ □ □ □ □ □

2.□ □ □ □ □ □ □ □ □

```
[CHG] Device 6A:45:32:E6:AE:94 RSSI: -90
[CHG] Device 5D:FD:0C:47:92:94 RSSI: -76
[CHG] Device 4D:47:F2:FA:5B:7C RSSI: -96
[CHG] Device 4D:47:F2:FA:5B:7C TxPower: 12
[CHG] Device 51:3B:36:78:C6:2C RSSI: -94
[CHG] Device 51:3B:36:78:C6:2C TxPower: 12
[CHG] Device 6A:D5:FA:7A:62:73 RSSI: -96
[CHG] Device 6A:D5:FA:7A:62:73 TxPower: 7
[CHG] Device 6A:D5:FA:7A:62:73 ManufacturerData Key: 0x004c
[CHG] Device 6A:D5:FA:7A:62:73 ManufacturerData Value:
10 05 71 18 ee ea b8 ..q....
[CHG] Device 62:33:09:A7:84:7C RSSI: -96
[CHG] Device 62:33:09:A7:84:7C TxPower: 12
```

```
90:F0:52:AD:5B:D8      MEIZU 18
root@LPA3568:/home/neardi# hcitool scan
Scanning ...
C4:40:F6:C9:FB:52      OPP0 Reno5 Pro 5G
90:F0:52:AD:5B:D8      MEIZU 18
8C:7A:AA:B2:61:68      不知道怎么设置轻点功能的AirPods Pro - Find My
A0:99:9B:05:1C:92      apple的MacBook Pro
10:2D:41:6D:5E:FE      65D8K_913F
connect 38:FB:14:F8:23:06 HONOR 9X
B0:BE:83:4F:43:03      Dahua的MacBook Pro
A8:98:92:D7:BD:96      n/a
D8:1E:DD:86:C3:BE      OPP0 Reno Z
8C:7A:AA:B2:61:68
28:39:26:29:CC:C4      n/a
root@LPA3568:/home/neardi# connect 8C:7A:AA:B2:61:68
-bash: connect: command not found
root@LPA3568:/home/neardi# bluetoothctl
Agent registered
[CHG] Controller 60:FB:00:4A:39:A7 Discoverable: no
[NEW] Device 28:39:26:29:CC:C4 DESKTOPNV8ATOL
[DESKTOPNV8ATOL]# connect 8C:7A:AA:B2:61:68
Attempting to connect to 8C:7A:AA:B2:61:68
[CHG] Device 28:39:26:29:CC:C4 Connected: no
3:000000000000150kb000000
```

History

#1 - 09/04/2024 10:57 AM - EGON

000000
hciconfig hci0 up -- hcitool scan -- connect <mac00>

#2 - 09/04/2024 11:04 AM - EGON

- Priority changed from Normal to High

#3 - 10/10/2024 07:00 PM - EGON

- Category changed from Driver to S.W
- Assignee changed from 00 to jing

#4 - 10/14/2024 03:23 PM - EGON

- Assignee changed from jing to 00

#5 - 10/14/2024 04:27 PM - EGON

- Status changed from New to Closed

Files

000000_17253608509174.png	28 KB	09/04/2024	EGON
000000_17254182233525.png	43.4 KB	09/04/2024	EGON