

WiFi - Bug #552

FD7352P STA ac-80 iperf3

09/12/2024 10:26 AM -

Status:	New	Start date:	09/12/2024
Priority:	High	Due date:	
Assignee:	KuangJie	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:		:	Ubuntu
CPU:	RK3399Pro	:	18.04
:		APP:	
/:		:	100%
:	02	:	
/:		:	
:	update-pcie.img	EMMC:	
Description			
1 iperf3 -c 192.168.0.3 -P 6 -b 1000M -t 60 -i 1 -w 2M			
2			

History

#1 - 09/12/2024 10:31 AM -

- File clipboard-202409121030-sjwvg.png added
- Subject changed from FD7352P STA ac-80 iperf3 to FD7352P STA ac-80 iperf3

```
[ 253.852788] pc : skw_pcie_read32+0x28/0x34 [skw_pcie]
[ 253.853241] lr : edma_get_node_tot_cnt+0x28/0x3c [skw_pcie]
[ 253.853731] sp : ffffffff00b22b00
[ 253.854029] x29: ffffffff00b22b00 x28: ffffffff800d19228
[ 253.854501] x27: 0000000000000000 x26: ffffffff800d197e0
[ 253.854972] x25: ffffffff800d19228 x24: 00000000000001300
[ 253.855443] x23: ffffffff800d11c140 x22: ffffffff800d19ce8
[ 253.855914] x21: ffffffff009eb6000 x20: ffffffff0012b7a08
[ 253.856385] x19: 0000000000000000 x18: 0000000000000000
[ 253.856856] x17: 0000000000000000 x16: 0000000000000000
[ 253.857326] x15: 0000000000000000 x14: ffffffff8002daa00
[ 253.857797] x13: ffffffff07615c000 x12: 0000000034d4d91d
[ 253.858268] x11: 0000000000000000 x10: 0000000000000990
[ 253.858739] x9 : ffffffff001241a0c x8 : 00000000000003ca0
[ 253.859209] x7 : 0000000000000000 x6 : 000000000000003f
[ 253.859680] x5 : 0000000000000040 x4 : 0000000000000f18
[ 253.860151] x3 : 0000000000000000 x2 : 0000000000000000
[ 253.860621] x1 : ffffffff00b800000 x0 : ffffffff00b988a4c
[ 253.861092] Call trace:
[ 253.861321] skw_pcie_read32+0x28/0x34 [skw_pcie]
[ 253.861752] skw_tx_worker+0x480/0x1074 [skw6316]
[ 253.862169] process_one_work+0x20c/0x49c
[ 253.862525] worker_thread+0x1a0/0x534
[ 253.862860] kthread+0x130/0x134
[ 253.863150] ret_from_fork+0x10/0x34
[ 253.863472]
[ 253.863472] PC: 0xffffffff001240398:
[ 253.863905] 0198 b0000061 d0000060 91082021 52801e82 91184000 95fee15e 17ffffffa b0000061
[ 253.864636] 01b8 d0000060 91082021 52802222 911a0000 95fee157 17ffffffb b0000061 d0000060
[ 253.865364] 01d8 91082021 52802082 91196000 95fee150 17ffffffd2 d503201f aa1e03e9 d503201f
[ 253.866093] 01f8 d2820082 8b020023 2a0003a2 d503233f 72800282 b9000062 d2820103 d360fc00
[ 253.866821] 0218 8b030022 b9000040 d2820184 52800000 8b040022 b9000040 52800020 91004422
[ 253.867549] 0238 b9000040 d2821085 52800362 8b050023 b9000062 d2821106 52801002 8b060023
[ 253.868278] 0258 b9000062 d2821187 8b070022 b900005f d2821208 8b080022 b900005f d2821309
[ 253.869006] 0278 52801fe2 8b090023 b9000062 d282100a 8b0a0021 b9000020 d50323bf d65f03c0
[ 253.869735] 0298 d503201f d503201f aa1e03e9 d503201f d503233f a9be7bfd 900000a0 910003fd
[ 253.870463] 02b8 a90153f3 f9424014 79400033 94002247 37180320 b9402a81 13017e60 7100043f
[ 253.871191] 02d8 1a930000 51000401 7100043f 54000169 51004400 7100141f 54000109 2a1303e0
[ 253.871920] 02f8 94000e6e 52800020 a94153f3 a8c27bfd d50323bf d65f03c0 2a1303e0 94000fe7
[ 253.872649] 0318 52800020 a94153f3 a8c27bfd d50323bf d65f03c0 b0000061 91082021 91004021
[ 253.873375] 0338 2a1303e3 d0000060 52800aa2 911a8000 95fee0f7 17ffffff0 aa1e03e9 d503201f
[ 253.874105] 0358 900000a0 d503233f d50323bf f9424000 d65f03c0 d503201f aa1e03e9 d503201f
[ 253.874833] 0378 90000001 d503233f f9424021 f9404000 91001309 b9000013 d5032e9f
[ 253.875562] 0398 b9400000 d50323bf d65f03c0 aa1e03e9 d503201f d503233f a9be7bfd 910003fd
[ 253.876290] 03b8 f9000bf3 2a0003f3 94002208 37180560 52900080 72a80300 97ffffe8 340000e0
[ 253.877018] 03d8 94001032 52800020 f9400bf3 a8c27bfd d50323bf d65f03c0 52800a00 72a80320
[ 253.877747] 03f8 97ffffde 72181c1f 54ffffe0 52800a00 72a80320 97ffffd9 d3483c13 940021f3
[ 253.878476] 0418 371801e0 90000080 f9424000 f9404000 91001309 b9000013 d5032e9f
[ 253.879205] 0438 52800020 f9400bf3 a8c27bfd d50323bf d65f03c0 b0000061 91082021 91000821
[ 253.879934] 0458 2a1303e3 d0000060 52800c82 911b2000 95fee0af 17ffffec b0000061 91082021
[ 253.880662] 0478 2a1303e3 9100a021 d0000060 52800da2 911a8000 95fee0a6 17ffffffc aa1e03e9
[ 253.881391] 0498 d503201f d503233f a9bd7bfd 910003fd a90153f3 d102c013 f9403c14 940021cb
[ 253.882120] 04b8 37180560 b4000593 91004281 aa1303e0 f90013f5 950a2e9 aa1303e0 950a0653
[ 253.882849] 04d8 52800001 aa1303e0 950a0653 940021be 37180780 52800002 52800001
[ 253.883578] 04f8 aa1303e0 950d0d09 2a0003f3 940021b7 37180580 f9400e80 f9404681 97ffff37
[ 253.884306] 0518 94001432 52902c00 72a80200 97ffff93 900000a1 12185c00 f9424021 f9404021
[ 253.885034] 0538 91442021 91058021 b9000020 d5032e9f 52800013 940021a5 37180220 f94013f5
[ 253.885762] 0558 2a1303e0 a94153f3 a8c37bfd d50323bf d65f03c0 12800253 17ffffffa b0000061
```

Files

clipboard-202409121030-sjwvg.png	143 KB	09/12/2024	
----------------------------------	--------	------------	--