

LP122 - Bug #557

-40°C 无wifi

09/18/2024 03:12 PM - EGON

Status:	Closed	Start date:	09/18/2024
Priority:	Normal	Due date:	
Assignee:	Linx	% Done:	0%
Category:	S.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
OS:	LP122	OS:	Ubuntu
CPU:	RK3568	Kernel:	Linux version 4.19.232 (wangxiaocan@ubuntu2004) (gcc version 6.3.1 20170404 (Linaro GCC 6.3-2017.05), GNU ld (Linaro_Binutils-2017.05) 2.27.0.20161019) #20 SMP Thu May 23 13:50:25 CST 2024
Board:	LPA3568J	APP:	
Bootloader:	04	Bootloader:	<20%
Kernel:	04	Kernel:	
Bootloader:	03	Kernel:	
Kernel:	\\192.168.1.250\17-OpenImage\neardi-download\RK3568\LPB3568\ubuntu\LPB3568_ubuntu20.04_HDMI_v1.0_20240524_1358	EMMC:	

Description

-40°C无wifi 无wifi ifconfig wlan0 ip

!%E4%BC%81%E4%B8%9A%E5%BE%AE%E4%BF%A1%E6%88%AA%E5%9B%BE_17262239919351.png!

History

- #1 - 09/18/2024 03:13 PM - EGON
无wifi--无wifi--ifconfig wlan0 ip
- #2 - 09/25/2024 04:17 PM - Linx
无wifi (-40°C) 无wifi
- #3 - 10/29/2024 09:37 AM - EGON
- CPU changed from RK3568J to RK3568
- #4 - 01/15/2025 09:51 AM - EGON
- 无wifi changed from LPM3568J to LPA3568J
- #5 - 01/15/2025 09:51 AM - EGON
- Status changed from New to Closed

Files

无wifi_17262239919351.png	72.8 KB	09/18/2024	EGON
--------------------------	---------	------------	------