

LP11A - Bug #560

Maskrom IDB

09/19/2024 10:56 AM -

Status:	Closed	Start date:	09/19/2024
Priority:	High	Due date:	
Assignee:	jing	% Done:	0%
Category:	H.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
OS:		OS:	Ubuntu
CPU:	RK3399Pro	APP:	
Board:		Board:	
Maskrom IDB:	01	Maskrom IDB:	
Loader:	03	Loader:	
EMMC:	LP11A_3399pro_ubuntu_test_v1.0_20240726.img	EMMC:	

Description

DDR4LP11A70MaskromIDB

瑞芯微开发工具 v2.91

下载镜像 升级固件 高级功能

固件 升级 切换

固件版本: 1.4.00 Loader版本: 1.0f 芯片信息: RK330C

固件: 测试固件\24-07-26\LP11A_3399pro_ubuntu_test_v1.0_20240726.img

发现一个MASKROM设备

2-2 :MASKROM

下载Boot开始
下载Boot成功
等待Maskrom开始
等待Maskrom成功
测试设备开始
测试设备成功
校验芯片开始
校验芯片成功
获取FlashInfo开始
获取FlashInfo成功
准备IDB开始
准备IDB失败
提示:请检查Flash是否在支持列表或者硬件虚焊

History

#1 - 09/19/2024 05:16 PM -

- Status changed from New to Closed

EMMCOKEMMC

Files

clipboard-202409191048-rva8c.png	68.9 KB	09/19/2024	
----------------------------------	---------	------------	--