

LP122 - Bug #565

USB

09/27/2024 10:00 AM - EGON

Status:	New	Start date:	09/27/2024
Priority:	Urgent	Due date:	
Assignee:	sun	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LP122	:	Ubuntu
CPU:	RK3568	:	Linux version 4.19.232 (wangxiaocan@ubuntu2004) (gcc version 6.3.1 20170404 (Linaro GCC 6.3-2017.05), GNU ld (Linaro_Binutils-2017.05) 2.27.0.20161019) #20 SMP Thu May 23 13:50:25 CST 2024
:	LPM3568J	APP:	
/:	04	:	<20%
:	04	:	
/:	03	:	
:	\\192.168.1.250\17-OpenImage\neardi-d ownload\RK3568\LPB3568\ubuntu\LPB3 568_ubuntu20.04_HDMI_v1.0_2024052 4_1358	EMMC:	

Description

USB

onsViewSplitMultiExecTunnelingPackagesSettingsHelp

44. Serial (COM)

45. Serial (COM)

31. 192.168.1

idgeidge (

2024-09-19 09:01:07 USB2.0 FAIL_B1B4

2024-09-19 09:03:24 USB2.0 FAIL_B1B4

2024-09-19 09:05:40 USB2.0 FAIL_B1B4

2024-09-19 09:07:57 USB2.0 FAIL_B1B4

2024-09-19 09:10:14 USB2.0 FAIL_B1B4

2024-09-19 09:12:27 USB2.0 PASS

2024-09-19 09:14:40 USB2.0 PASS

2024-09-19 09:16:53 USB2.0 FAIL_B1B4

2024-09-19 09:17:06 USB2.0 FAIL_B1B4

2024-09-19 09:19:10 USB2.0 FAIL_B4

2024-09-19 09:21:23 USB2.0 FAIL_B1B4

2024-09-19 09:23:36 USB2.0 FAIL_B1B4

2024-09-19 09:25:48 USB2.0 FAIL_B1B4

2024-09-19 09:28:01 USB2.0 FAIL_B1B4

2024-09-19 09:30:14 USB2.0 FAIL_B1B4

2024-09-19 09:32:27 USB2.0 FAIL_B1B4

2024-09-19 09:34:41 USB2.0 FAIL_B1B4

2024-09-19 09:36:54 USB2.0 FAIL_B1B4

2024-09-19 09:56:46 USB2.0 PASS

2024-09-19 09:59:00 USB2.0 PASS

2024-09-19 10:01:43 USB2.0 PASS

2024-09-19 10:03:42 USB2.0 FAIL_B5B4

2024-09-19 10:05:35 USB2.0 PASS

2024-09-19 10:07:28 USB2.0 PASS

2024-09-19 10:09:21 USB2.0 PASS

2024-09-19 10:11:14 USB2.0 PASS

2024-09-19 10:13:09 USB2.0 FAIL_B5B4

2024-09-19 10:15:02 USB2.0 PASS

2024-09-19 10:16:55 USB2.0 PASS

2024-09-19 10:18:48 USB2.0 PASS

2024-09-19 10:20:41 USB2.0 PASS

2024-09-19 10:22:34 USB2.0 PASS

2024-09-19 10:25:31 USB2.0 PASS

2024-09-19 10:28:41 USB2.0 PASS

2024-09-19 10:30:35 USB2.0 FAIL_B5B4

2024-09-19 10:32:28 USB2.0 FAIL_B1B4

2024-09-19 10:34:20 USB2.0 FAIL_B4

2024-09-19 10:36:12 USB2.0 FAIL_

2024-09-19 10:38:03 USB2.0 FAIL_

2024-09-19 10:51:00 USB2.0 B1B4

History

#1 - 09/27/2024 10:06 AM - EGON

|||||
lsust -t | grep "USB2.0" | wc -l ----lsust -t | grep "USB3.0" | wc -l
USB2.0 3
USB3.0 2

#2 - 09/29/2024 06:41 PM - EGON

- Priority changed from Normal to Urgent

#3 - 10/29/2024 09:36 AM - EGON

- CPU changed from RK3588 to RK3568

Files

_17267970606836.png	70 KB	09/27/2024	EGON
---------------------	-------	------------	------