

LP120 - Bug #573

vedio8

10/10/2024 10:22 AM - EGON

Status:	Closed	Start date:	10/10/2024
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LP120	:	Ubuntu
CPU:	RK3568	:	Linux version 5.10.198 (yangyonghao@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #4 SMP Wed Oct 9 14:17:20 CST 2024
:	LPA3568M8	APP:	
/:	04	:	<50%
:	04	:	
/:	05	:	
:	\\192.168.1.250\01-Public\wilson_test\rk 3568\lpa3568\LP120_Ubuntu20.04_v1.0 _20240929	EMMC:	

Description

vedio8



History

#1 - 10/10/2024 10:40 AM - EGON

- changed from 100% to <50%

gst-launch-1.0 -v v4l2src device=/dev/video8 ! video/x-raw, format=NV12,width=1280, height=720, framerate=30/1 ! fpsdisplaysink sync=false text-overlay=false

#2 - 10/15/2024 10:28 AM - EGON

- Status changed from New to Closed

Files

17285268166606.png	424 KB	10/10/2024	EGON
--------------------	--------	------------	------