

LPM3568 - Bug #599

ETH3 100M

11/07/2024 04:07 PM - mike

Status: Closed	Start date: 11/04/2024
Priority: Normal	Due date:
Assignee: []	% Done: 0%
Category: Driver	Estimated time: 0.00 hour
Target version:	Spent time: 0.00 hour
OS: LD125	OS: Ubuntu
CPU: LCB3568	OS version: Linux version 5.10.160 (yangyonghao@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #16 SMP Tue Oct 29 15:40:39 CST 2024
Model: LKD3568 []	APP:
OS/Kernel:	APP version: 100%
OS/Kernel: 04	APP:
OS/Kernel: 01	APP:
Path: \\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	EMMC:

Description

ETH3 100M

```
root@LPA3568:~# cat /sys/class/net/eth3/speed
100
root@LPA3568:~#
```

History

#1 - 11/08/2024 10:23 AM - Linx

[]

#2 - 11/08/2024 11:51 AM - jing

[] USB2.0 []

#3 - 11/08/2024 11:56 AM - EGON

- Category changed from S.W to Driver

- Assignee changed from Linx to []

#4 - 11/11/2024 11:21 AM - EGON

- Status changed from New to Closed

Files

[]_17307052928691.png	3.94 KB	11/04/2024	EGON
------------------------	---------	------------	------