

LPM3568 - Bug #605

HDMI

11/08/2024 06:07 PM - EGON

Status:	New	Start date:	11/08/2024
Priority:	Normal	Due date:	
Assignee:	Linx	% Done:	0%
Category:	S.W	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
:	LD125	:	Ubuntu
CPU:	RK3568	:	Linux version 5.10.160 (yangyonghao@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #16 SMP Tue Oct 29 15:40:39 CST 2024
:	LKD3568	APP :	
/ :		:	100%
:	03	:	
/ :	01	:	
:	\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\Test	EMMC :	
Description			
HDMI			

History

- #1 - 11/28/2024 08:41 PM -
- sdksdk5.10.198 hdmi sound5.10.160 hdmi sound
- #2 - 11/28/2024 08:43 PM -
- sdksdk
- #3 - 11/28/2024 09:56 PM -
- sdksdk\\192.168.1.250\01-Public\wilson_test\rk3568\lp125\2024_11_28
- #4 - 11/29/2024 10:09 AM - EGON
- Category changed from Driver to S.W
- Assignee changed from to Linx
- hdmi gst-play-1.0 /home/neardi/Desktop/sony1.mp4
- hdmi HDMI aplay -D plughw:1,0 /home/neardi/Desktop/ch-test.wav