

LPM3568 - Bug #608


□ □ □ □ □ □ □ □ □ □

11/08/2024 06:56 PM - EGON

Status:	New	Start date:	11/08/2024
Priority:	Normal	Due date:	
Assignee:	□ □	% Done:	0%
Category:	Driver	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
□ □ :	LD125	□ □ :	Ubuntu
CPU:	RK3568	□ □ □ □ :	Linux version 5.10.160 (yangyonghao@ubuntu2004) (aarch64-none-linux-gnu-gcc (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 10.3.1 20210621, GNU ld (GNU Toolchain for the A-profile Architecture 10.3-2021.07 (arm-10.29)) 2.36.1.20210621) #16 SMP Tue Oct 29 15:40:39 CST 2024
□ □ :	LKD3568□ □ □	APP□ □ :	
□ □ /□ □ □ □ □ □ :		□ □ □ □ :	100%
□ □ □ □ □ □ :	03	□ □ □ □ :	FD7256S
□ □ /□ □ □ □ □ □ :	01	□ □ □ □ □ :	
□ □ □ □ :	\\192.168.1.250\01-Public\wilson_test\rk 3568\lp125\Test	EMMC□ □ :	

Description

□ □ □ □ □ □ □ □ □ □



History

#1 - 11/26/2024 02:31 PM - EGON

- File□ □ □ □ □ □_1732602670635.png added
- File□ □ □ □ □ □_17326026617317.png added
- File□ □ □ □ □ □_17326026852087.png added

!%E4%BC%81%E4%B8%9A%E5%BE%AE%E4%BF%A1%E6%88%AA%E5%9B%BE_1732602670635.png!
!%E4%BC%81%E4%B8%9A%E5%BE%AE%E4%BF%A1%E6%88%AA%E5%9B%BE_17326026617317.png!
!%E4%BC%81%E4%B8%9A%E5%BE%AE%E4%BF%A1%E6%88%AA%E5%9B%BE_17326026852087.png!

- set to FD7256S

50LPM35686101M

Files			
_1731062837653.png	368 KB	11/08/2024	EGON
_17310633432990.png	369 KB	11/08/2024	EGON
_1732602670635.png	209 KB	11/26/2024	EGON
_17326026617317.png	91.4 KB	11/26/2024	EGON
_17326026852087.png	77.9 KB	11/26/2024	EGON